

1R - 187

# REPORTS

DATE:

4/8/98

NEW MEXICO OIL CONSERVATION COMMISSION  
FIELD TRIP REPORT

4-9-98

Name WAYNE PRICE

Date 4/8/98

Miles \_\_\_\_\_ District I

Time of Departure 7 AM

Time of Return 4 PM

Car No. G 04721

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature [Signature]

MMC- SITE INSPECTION WITH  
NMOC-D-SF FORD & ANDERSON, & OLSON

TOOK PICTURES!

MET BOB WORLEY - MMC - RECOMMEND FOR  
AIA TO DE-CANT ALL  
PODS!

Mileage

UIC \_\_\_\_\_  
RFA \_\_\_\_\_  
Other \_\_\_\_\_

Per Diem

UIC \_\_\_\_\_  
RFA \_\_\_\_\_  
Other \_\_\_\_\_

Hours

UIC \_\_\_\_\_  
RFA \_\_\_\_\_  
Other \_\_\_\_\_

TYPE INSPECTION  
PERFORMED

H = Housekeeping  
P = Plugging  
C = Plugging Cleanup  
T = Well Test  
R = Repair/Workover  
F = Waterflow  
M = Mishap or Spill  
W = Water Contamination  
O = Other

INSPECTION  
CLASSIFICATION

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
R = Inspections relating to Reclamation Fund Activity  
O = Other - Inspections not related to injection or The Reclamation Fund  
E = Indicates some form of enforcement action taken in the field (show immediately below the letter U, R or O)

NATURE OF SPECIFIC WELL  
OR FACILITY INSPECTED

D = Drilling  
P = Production  
I = Injection  
C = Combined prod. inj. operations  
S = SWD  
U = Underground Storage  
G = General Operation  
F = Facility or location  
M = Meeting  
O = Other



NMOCB: ID#, 813548 By: W Price #1  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking SSW, UMC Snubbing  
unit, Carlise Windmill in Bkgd.

010.2002 11-01 110000-1000 01



NMOCID: ID#. 813548 By: W Price #1  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking SSW. UMC Snubbing  
unit. Carlise Windmill in Bkgd.



NMOCB: ID#. 813548 By: W Price #2  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking SSW. UMC Snubbing  
unit. Carlise Windmill in Bkgd.





HMOCB: ID#. 813548 By: W Price #2  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking SSW. UMC Snubbing  
unit. Carlise Windmill in Bkgd.



900 40 006

NMOCB: ID#. 813548 By: W Price #3  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking E. East flare pit  
and East ponds.

32711 003



HMOCB: ID#. 813548 By: W Price #3  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking E. East flare pit  
and East ponds.



NMOCD: ID#. 813548 By: W Price #4  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking SE. East ponds  
unlined. Jack Ford NMOCD





NMOCD: ID#. 813548 By: W Price #4  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking SE. East ponds  
unlined. Jack Ford NMOCD



010-0-010  
NMOCB: ID#. 813548 By: W Price #5  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking SE East Ponds.  
L-R Ford,olson,anderson-NMOCB  
02701 095



NMOCD: ID#, 813548 By: W Price #5  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking SE East Ponds,  
L-R Ford,olson,anderson-NMOCD





NMOCD: ID#, 813548 By: W Price #6  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking North south of well  
Carlise stock pond. Visually impacted.





NMOCD: ID#. 813548 By: W Price #6  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking North south of well  
Carlise stock pond. Visually impacted..



NMOCID: ID#, 813548 By: W Price #7  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking NE. south of well  
Carlise stock pond. Visually impacted.



NMOCID: ID#. 813548 By: W Price #7  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking NE, south of well  
Carlise stock pond. Visually impacted..





NMOCID: ID#. 813548 By: W Price #8  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking NE. SW of well near  
drilling pits. Soil is contaminated.





NMOCID: ID#, 813548 By: W Price #8  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking NE. SW of well near  
drilling pits. Soil is contaminated.



NMOCB: ID#. 813548 By: W Price #9  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking NNW West of Drill  
pit. Emer. condensate pit unlined.



NMOCB: ID#. 813548 By: W Price #9  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking NNW West of Drill  
pit. Emer. condensate pit unlined.





NMOCD: ID#. 813548 By: W Price #10  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking NE. SW of well,  
shows drilling pits. Liners burned.





HMOCID: ID#. 813548 By: W Price #10  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking NE. SW of well,  
shows drilling pits. Liners burned.



QNo. 120 022  
NMOCB: ID#. 813548 By: W Price #11  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking N. SW of well,  
shows drilling pits. Liners burned.

5011 0503



HMOCB: ID#, 813548 By: W Price #11  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking N. SW of well.  
shows drilling pits. Liners burned.



OVER SPRAY AREA



HMOCID: ID#. 813548 By: W Price #12  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-Ts16s-R35e  
Location: UMC Blow-out area  
Subject: Looking N. Shows Condensate over spray area on vegetation.



OVER SPRAY AREA



HMUCD: ID#. 813548 By: W Price #12  
Date/Time: April 8, 1998 4pm  
Site/Co. UMC K-sec10-1s16s-R35e  
Location: UMC Blow-out area  
Subject: Looking N. Shows Condensate over spray area on vegetation.

