


1R -

338

GENERAL CORRESPONDENCE

YEAR(S):

2001



Inspect Facility

Surface Facilities

Facility ID	FLWP0134650876	Fac Name	Santa Pacific RR #122	UL-S-T-R	P
Bond No		Fac Type	Tank Battery	Status	A
Disp Mthd		Company	OIL DEVELOPMENT CO OF TEXAS	County	Lea
DATE	Open	Wtr Source		Location (Qtr/Qtr)	
YES	Closed	Wtr Volume	0	Dischrg Qlty	
	Sys Review	GW Depth	0	GW Quality	
	Surf Own	Notes		Permits on T	
	Directions			1RP	338 0
				GW Impact?	



Tanks



Pits




Sumps

Tank No		Type		Construction		Base	
Volume		bbls	Fluid Type		Fluid Pad		ft Desc

Record: 14 of 1

Record: 14 of 1 (Filtered)

Bond Number



Well Selection Criteria

frmOrdMaster

RBDMS Surface

Oil Development of Texas
Santa Fe Pacific RR #122
SE/4 SE/4 Sec 22-9s-R36e

OCD Case # 1R0338

