

1R - 427 - 42

REPORTS

DATE:

10 - 15 - 2003

EME Chevron Orcutt ECL

1R0427-42

FINAL REPORT

**RICE OPERATING COMPANY
JUNCTION BOX FINAL REPORT**

BOX LOCATION

SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNTY	BOX DIMENSIONS - FEET		
							Length	Width	Depth
EME	Chevron Orcutt EOL	A	25	T21S	35E	Lea	Eliminated		

LAND TYPE: BLM _____ STATE X FEE LANDOWNER _____ OTHER _____

Depth to Groundwater 230 feet NMOCD SITE ASSESSMENT RANKING SCORE: 0

Date Started unknown Date Completed October 2003 OCD Witness No

Soil Excavated unknown cubic yards Excavation Length unknown Width unknown Depth unknown feet

Soil Disposed n/a cubic yards Offsite Facility n/a Location n/a

FINAL ANALYTICAL RESULTS: Sample Date n/a Sample Depth n/a

Procure 5-point composite sample of bottom and 4-point composite sample of sidewalls. TPH, BTEX and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines.

Sample Location	Benzene mg/kg	Toluene mg/kg	Ethyl Benzene mg/kg	Total Xylenes mg/kg	GRO mg/kg	DRO mg/kg	Chloride mg/kg
SIDEWALLS	n/a	n/a	n/a	n/a	n/a	n/a	n/a
BOTTOM	n/a	n/a	n/a	n/a	n/a	n/a	n/a
REMEDIATED	n/a	n/a	n/a	n/a	n/a	n/a	n/a

General Description of Remedial Action: When ROC removed the NORM from this EOL box, the Chevron Orcutt 'F' battery was already dismantled. The battery was remediated by Chevron-Texaco in late September and early October. The remediation encompassed the ROC EOL box.

CHLORIDE FIELD TESTS

LOCATION	DEPTH (ft)	ppm

enclosures: photos

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DATE 10/15/2003 PRINTED NAME Kristin Farris
SIGNATURE *Kristin Farris* TITLE Project Scientist

EME Chevron Orcutt 'F' EOL



Site of EOL Box After NORM Removal 5/5/2003



Backfilled Site After Remediation 10/7/2003



Backfilled Site After Remediation 10/7/2003