

1R - 427 - 63

REPORTS

DATE:

3-22-2002

1R0427-63

FINAL REPORT

**RICE OPERATING COMPANY
JUNCTION BOX FINAL REPORT**

BOX LOCATION

SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNTY	BOX DIMENSIONS - FEET		
EME	B-32	B	32	19S	37E	LEA	Length	Width	Depth

LAND TYPE: BLM _____ STATE X FEE LANDOWNER _____ OTHER _____

Depth to Groundwater <50 feet NMOCD SITE ASSESSMENT RANKING SCORE: 20

Date Started 2/13/2002 Date Completed 3/12/2002 OCD Witness NO

Soil Excavated 120 cubic yards Excavation Length 20 Width 20 Depth 8 feet

Soil Disposed 108 cubic yards Offsite Facility J & L / Sundance Location MONUMENT/EUNICE, NM

FINAL ANALYTICAL RESULTS: Sample Date 3/12/2002 Sample Depth 8'

Procure 5-point composite sample of bottom and 4-point composite sample of sidewalls. TPH, BTEX and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines.

Sample Location	Benzene mg/kg	Toluene mg/kg	Ethyl Benzene mg/kg	Total Xylenes mg/kg	GRO mg/kg	DRO mg/kg	Chlorides mg/kg
SIDEWALLS	<0.025	<0.025	<0.025	<0.025	<10	<10	595
BOTTOM	<0.025	<0.025	<0.025	<0.025	<10	<10	698
Boring @20'	<0.025	<0.025	<0.025	<0.025	<10	<10	22

General Description of Remedial Action: Delineated vertical and lateral extent.

Vertical delineation found TPH clean at 8' bgs. At 12' bgs chlorides were 450 ppm.

Completed a soil boring on 2/28/02 which demonstrated a drop in chlorides from 770 ppm at 5' to 100 ppm @ 20' bgs. These results indicate the impact stopped before reaching groundwater.

Hauled high impact soil to a permitted disposal facility. Installed a compacted clay barrier to vertical transmissivity and backfilled with fresh soil. This site is no longer a junction and and does not require a box.

CHLORIDE FIELD TESTS

LOCATION	DEPTH	mg/kg
SIDEWALLS	7'	600
BOTTOM	8'	650
Soil Boring	5'	770
	10'	340
	15'	90
	20'	100

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DATE March 22, 2002 PRINTED NAME D. E. Anderson

SIGNATURE *D. E. Anderson* TITLE Project Leader - Environmental

DRILLING LOG		Site Name/Location			Logged by: DEA			
RICE Operating Company 122 West Taylor Hobbs, New Mexico 88240 Phone: (505) 393-9174 Fax: (505) 397-1471		Jct. Box B-32 32-T19S-R37E EME SWD System Lea County, NM			Well No: N/A Well Depth: N/A Casing Length: N/A Screen Length: N/A	Date Drilled: 2/28/02 Boring Depth: 20' Boring Diameter: 4.75" Drilling Method: Air Rotary	Driller: Eades Well Material: N/A Casing Size: N/A Slot Size: N/A	Construction: Plugged boring w/ 20' bentonite, water & backfill
TEST								
DEPTH	SUBSURFACE LITHOLOGY	SAMPLE TYPE	(ppm)	REMARKS	Boring			
0	Ground surface		Cl					
1	Topsoil							
2	Caliche							
3								
4								
5		Grab	770	Field Test	cuttings			
6								
7								
8								
9								
10		Grab	340	Field Test				
11								
12								
13								
14	Dry clay and sanstone stringers							
15		Grab	90	Field Test				
16								
17	Sandstone							
18	Sandy clay and sandstone stringers							
19								
20		Grab	100	Field Test				

ANALYTICAL REPORT

Prepared for:

DEREK ROBINSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Project: Rice *B-32*
Order#: G0202810
Report Date: 03/19/2002

Certificates

US EPA Laboratory Code TX00158

ENVIRONMENTAL LAB OF TEXAS**SAMPLE WORK LIST**

RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768
366-0804

Order#: G0202810
Project:
Project Name: Rice
Location: B-32

The samples listed below were submitted to Environmental Lab of Texas and were received under chain of custody. Environmental Lab of Texas makes no representation or certification as to the method of sample collection, sample identification, or transportation/handling procedures used prior to the receipt of samples by Environmental Lab of Texas.

<u>Lab ID:</u>	<u>Sample :</u>	<u>Matrix:</u>	<u>Date / Time</u> <u>Collected</u>	<u>Date / Time</u> <u>Received</u>	<u>Container</u>	<u>Preservative</u>
0202810-01	4 pt Wall Comp. @7'	SOIL	03/11/2002 13:00	03/12/2002 16:30	4 oz Glass	ice
<u>Lab Testing:</u>		Rejected: No	Temp: 22C			
8015M TPH GRO/DRO						
8021B/5030 BTEX						
Chloride						
0202810-02	5 pt. Bottom Comp. @8'	SOIL	03/12/2002 9:00	03/12/2002 16:30	4 oz Glass	ice
<u>Lab Testing:</u>		Rejected: No	Temp: 22C			
8015M TPH GRO/DRO						
8021B/5030 BTEX						
Chloride						

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

DEREK ROBINSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0202810
Project:
Project Name: Rice
Location: B-32

Lab ID: 0202810-01
Sample ID: 4 pt Wall Comp. @7'

8015M TPH GRO/DRO

Method <u>Blank</u>	Date <u>Prepared</u>	Date <u>Analyzed</u>	Sample <u>Amount</u>	Dilution <u>Factor</u>	Analyst	Method
		03/14/2002 15:13	1	1	CK	8015M

Parameter	Result mg/kg	RL
GRO, C6-C12	<10	10.0
DRO, >C12-C28	<10	10.0
Total C6-C28	<10	10.0

8021B/5030 BTEX

Method <u>Blank</u>	Date <u>Prepared</u>	Date <u>Analyzed</u>	Sample <u>Amount</u>	Dilution <u>Factor</u>	Analyst	Method
0000901-02		03/14/2002 17:28	1	1	CK	8021B

Parameter	Result µg/kg	RL
Benzene	<25.0	25.0
Ethylbenzene	<25.0	25.0
Toluene	<25.0	25.0
p/m-Xylene	<25.0	25.0
o-Xylene	<25.0	25.0

Lab ID: 0202810-02
Sample ID: 5 pt. Bottom Comp. @8'

8015M TPH GRO/DRO

Method <u>Blank</u>	Date <u>Prepared</u>	Date <u>Analyzed</u>	Sample <u>Amount</u>	Dilution <u>Factor</u>	Analyst	Method
		03/14/2002 15:23	1	1	CK	8015M

Parameter	Result mg/kg	RL
GRO, C6-C12	<10	10.0
DRO, >C12-C28	<10	10.0
Total C6-C28	<10	10.0

DL = Diluted out N/A = Not Applicable RL = Reporting Limit

Page 1 of 2

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

DEREK ROBINSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0202810
Project:
Project Name: Rice
Location: B-32

Lab ID: 0202810-02
Sample ID: 5 pt. Bottom Comp. @8'

8021B/5030 BTEX

Method <u>Blank</u>	Date <u>Prepared</u>	Date <u>Analyzed</u>	Sample <u>Amount</u>	Dilution <u>Factor</u>	Analyst	Method
0000901-02		03/14/2002 17:50	1	1	CK	8021B

Parameter	Result µg/kg	RL
Benzene	<25.0	25.0
Ethylbenzene	<25.0	25.0
Toluene	<25.0	25.0
p/m-Xylene	<25.0	25.0
o-Xylene	<25.0	25.0

Approval:

Coley Keene 3/19/02
Raland K. Tuttle, Lab Director, QA Officer
Coley D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Irene Perry, QA Assistant
Sandra Biezugbe, Lab Tech.
Curt Cowdrey, Lab Tech.
Sara Molina, Lab Tech.

Date

DL = Diluted out N/A = Not Applicable RL = Reporting Limit

Page 2 of 2

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

DEREK ROBINSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0202810
Project:
Project Name: Rice
Location: B-32

Lab ID: 0202810-01
Sample ID: 4 pt Wall Comp. @7'

Test Parameters

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Dilution Factor</u>	<u>RL</u>	<u>Method</u>	<u>Date Analyzed</u>	<u>Analyst</u>
Chloride	595	mg/kg	1	10	9253	03/18/2002	SB

Lab ID: 0202810-02
Sample ID: 5 pt. Bottom Comp. @8'

Test Parameters

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Dilution Factor</u>	<u>RL</u>	<u>Method</u>	<u>Date Analyzed</u>	<u>Analyst</u>
Chloride	698	mg/kg	1	10	9253	03/18/2002	SB

Approval:

Celey Keene 3/19/02
Raland K. Tuttle, Lab Director, QA Officer
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Irene Perry, QA Assistant
Sandra Biezugbe, Lab Tech.
Curt Cowdrey, Lab Tech.
Sara Molina, Lab Tech.

Date

RL = Reporting Limit N/A = Not Applicable

Page 1 of 1

ENVIRONMENTAL LAB OF TEXAS**QUALITY CONTROL REPORT****8015M TPH GRO/DRO****Order#: G0202810**

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Total C6-C28-mg/kg	0000871-02			<10		
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Total C6-C28-mg/kg	0202809-05	0	952	942	98.9%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Total C6-C28-mg/kg	0202809-05	0	952	940	98.7%	0.2%
SRM	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Total C6-C28-mg/kg	0000871-05		1000	1039	103.9%	0.0%

ENVIRONMENTAL LAB OF TEXAS**QUALITY CONTROL REPORT****8021B/5030 BTEX****Order#: G0202810**

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-µg/kg	0000901-02			<25.0		
Ethylbenzene-µg/kg	0000901-02			<25.0		
Toluene-µg/kg	0000901-02			<25.0		
p/m-Xylene-µg/kg	0000901-02			<25.0		
o-Xylene-µg/kg	0000901-02			<25.0		
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-µg/kg	0202807-07	0	100	97.8	97.8%	
Ethylbenzene-µg/kg	0202807-07	0	100	97.9	97.9%	
Toluene-µg/kg	0202807-07	0	100	98.6	98.6%	
p/m-Xylene-µg/kg	0202807-07	0	200	202	101.1%	
o-Xylene-µg/kg	0202807-07	0	100	97.9	97.9%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-µg/kg	0202807-07	0	100	94.5	94.5%	3.4%
Ethylbenzene-µg/kg	0202807-07	0	100	95.1	95.1%	2.9%
Toluene-µg/kg	0202807-07	0	100	96.2	96.2%	2.5%
p/m-Xylene-µg/kg	0202807-07	0	200	197	98.5%	2.5%
o-Xylene-µg/kg	0202807-07	0	100	95.3	95.3%	2.7%
SRM	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-µg/kg	0000901-05		100	113	113.1%	0.0%
Ethylbenzene-µg/kg	0000901-05		100	111	111.1%	0.0%
Toluene-µg/kg	0000901-05		100	114	114.1%	0.0%
p/m-Xylene-µg/kg	0000901-05		200	230	115.1%	0.0%
o-Xylene-µg/kg	0000901-05		100	113	113.1%	0.0%

ENVIRONMENTAL LAB OF TEXAS**QUALITY CONTROL REPORT****Test Parameters**

Order#: G0202810

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0000902-01			<5.00		
CONTROL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0000902-02		5000	5050	101.4%	
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0202812-01	886	556	1450	101.4%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0202812-01	886	556	1460	103.2%	0.7%

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

Sampler Signature:

[illegible]

ANALYTICAL REPORT

Prepared for:

DONNIE ANDERSON
RICE OPERATING CORP.
122 WEST TAYLOR
HOBBS, NM 88242

Project: Jct B-32 Soil bore box Upgrade
Order#: G0202743
Report Date: 03/07/2002

Certificates

US EPA Laboratory Code TX00158

ENVIRONMENTAL LAB OF TEXAS

SAMPLE WORK LIST

RICE OPERATING CORP.
122 WEST TAYLOR

HOBBS, NM 88242

Order#: G0202743

Project: Soil bore @ 20'
bgs

Project Name: Jct B-32 Soil bore box Upgrade

Location: EME

The samples listed below were submitted to Environmental Lab of Texas and were received under chain of custody. Environmental Lab of Texas makes no representation or certification as to the method of sample collection, sample identification, or transportation/handling procedures used prior to the receipt of samples by Environmental Lab of Texas.

			Date / Time	Date / Time		
0202743-01	Soil bore @ 20' bgs	SOIL		3/5/02	4 oz Glass	ice
				17:00		
	<u>Lab Testing:</u>	Rejected: No		Temp: 7C		
	8015M TPH GRO/DRO					
	8021B/5030 BTEX					
	Chloride					

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

DONNIE ANDERSON
RICE OPERATING CORP.
122 WEST TAYLOR
HOBBS, NM 88242

Order#: G0202743
Project: Soil bore @ 20' bgs
Project Name: Jet B-32 Soil bore box Upgrade
Location: EME

Lab ID: 0202743-01
Sample ID: Soil bore @ 20' bgs

8015M TPH GRO/DRO

Method	Date	Date	Sample	Dilution		
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>	<u>Analyst</u>	<u>Method</u>
0000785-02		3/6/02 14:21	1	1	CK	8015

Parameter	Result mg/kg	RL
GRO, C6-C12	<10	10.0
DRO, >C12-C28	<10	10.0

8021B/5030 BTEX

Method	Date	Date	Sample	Dilution		
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>	<u>Analyst</u>	<u>Method</u>
0000783-02		3/6/02 16:56	1	1	CK	8021B

Parameter	Result µg/kg	RL
Benzene	<25	25.0
Ethylbenzene	<25	25.0
Toluene	<25	25.0
p/m-Xylene	<25	25.0
o-Xylene	<25	25.0

Approval:

Raland K. Tuttle

3-07-02

Raland K. Tuttle, Lab Director, QA Officer
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Irene Perry, QA Assistant
Sandra Biezugbe, Lab Tech.
Curt Cowdrey, Lab Tech.
Sara Molina, Lab Tech.

Date

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

DONNIE ANDERSON
RICE OPERATING CORP.
122 WEST TAYLOR
HOBBS, NM 88242

Order#: G0202743
Project: Soil bore @ 20' bgs
Project Name: Jet B-32 Soil bore box Upgrade
Location: EME

Lab ID: 0202743-01
Sample ID: Soil bore @ 20' bgs

Test Parameters

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Dilution Factor</u>	<u>RL</u>	<u>Method</u>	<u>Date Analyzed</u>	<u>Analyst</u>
Chloride	22.0	mg/kg	1	5.0	9253	3/6/02	SB

Approval: Raland K. Tuttle 3-07-02
Raland K. Tuttle, Lab Director, QA Officer Date
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Irene Perry, QA Assistant
Sandra Biezugbe, Lab Tech.
Curt Cowdrey, Lab Tech.
Sara Molina, Lab Tech.

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

8015M TPH GRO/DRO

Order#: G0202743

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0000785-02			<10		
DRO, >C12-C28-mg/kg	0000785-02			<10		
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0202740-01	0	476	447	93.9%	
DRO, >C12-C28-mg/kg	0202740-01	0	476	563	118.3%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0202740-01	0	476	424	89.1%	5.3%
DRO, >C12-C28-mg/kg	0202740-01	0	476	506	106.3%	10.7%
SRM	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0000785-05		500	441	88.2%	0.9%
DRO, >C12-C28-mg/kg	0000785-05		500	524	104.8%	0.9%

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

8021B/5030 BTEX

Order#: G0202743

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-μg/kg	0000783-02			<25		
Ethylbenzene-μg/kg	0000783-02			<25		
Toluene-μg/kg	0000783-02			<25		
p/m-Xylene-μg/kg	0000783-02			<25		
o-Xylene-μg/kg	0000783-02			<25		
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-μg/kg	0202728-02	0	100	112	112.0%	
Ethylbenzene-μg/kg	0202728-02	0	100	111	111.0%	
Toluene-μg/kg	0202728-02	0	100	113	113.0%	
p/m-Xylene-μg/kg	0202728-02	0	200	230	115.0%	
o-Xylene-μg/kg	0202728-02	0	100	112	112.0%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-μg/kg	0202728-02	112	100	113	113.0%	0.9%
Ethylbenzene-μg/kg	0202728-02	111	100	112	112.0%	0.9%
Toluene-μg/kg	0202728-02	113	100	113	113.0%	0.0%
p/m-Xylene-μg/kg	0202728-02	230	200	228	114.0%	0.9%
o-Xylene-μg/kg	0202728-02	112	100	114	114.0%	1.8%
SRM	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-μg/kg	0000783-05		100	112	112.0%	0.0%
Ethylbenzene-μg/kg	0000783-05		100	111	111.0%	0.0%
Toluene-μg/kg	0000783-05		100	114	114.0%	0.0%
p/m-Xylene-μg/kg	0000783-05		200	229	114.5%	0.0%
o-Xylene-μg/kg	0000783-05		100	112	112.0%	0.0%

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

Test Parameters

Order#: G0202743

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0000787-01			<5.00		
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0202739-01	248	667	910	99.3%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0202739-01	248	667	922	101.0%	1.3%
SRM	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0000787-04		5000	5050	101.0%	0.0%

12500 West I-20 East
Odessa, Texas 79763
Phone: 915-563-1800
Fax: 915-563-1713

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

Sampler Signature:

Fax No: (505) 397-1471

Project Name: Jct B-3a soil bore boulevard

Project #: So: / bone @ 26' bgs

Project Loc: ENE

PO #:

[illegible]

Special Instructions:

Relinquished by:		Date	Time	Received by:		Date	Time
<i>[Signature]</i>		030502	1100	<i>[Signature]</i>		3-5-02	11:00 AM
<i>[Signature]</i>		3-5-02	5 PM	<i>[Signature]</i>		3-5-02	17:00



J & L LANDFARM, INC.

P.O. BOX 356
HOBBS, NEW MEXICO 88241-0356
PHONE (505) 393-9697 • PERMIT # NM-01-0023

0201

Generator/Company RICE OPERATING CO.

Authorized Representative DONNIE ANDERSON

Originating Site B-32
S-32 T 19 S R 37 E

Transporter R/E CONSTRUCTION

Authorized Representative Don Robinson

Brief Description of Material NON-HAZ SOIL

Estimated Volume 96 yards

TPH SEE TEST

BE-TEX " "

CERTIFICATE OF CHEMICAL ANALYSIS (if required) N/A

Lee M. Roberts
FACILITY AUTHORIZED REPRESENTATIVE

March 12 2002
DATE

Sundance Services, Inc.P.O. Box 1737 ★ Eunice, NM 88231
(505) 394-2511

NO 48799

LEASE OPERATOR/SHIPPER/COMPANY: RiceLEASE NAME: E.M.E. SWDTRANSPORTER COMPANY: DIT WORK

TIME: _____ AM/PM

DATE: 1/3/2VEHICLE NO.: 101

DRIVER NO.: _____

CHARGE TO: RiceTYPE OF MATERIAL S32 T20S R37E☐ Production Water☐ Tank Bottoms☐ Other Material:☐ Drilling Fluids☐ Contaminated soil☐ BS&W Content: _____☐ Completion Fluids☐ C-117 No.: _____Description: ODSYSTEM EME SWD
JOB B 32 WELL ASEA 716VOLUME OF MATERIAL ☐ BBLs. _____ :☐ YARD 12 _____ :☐ _____

AS A CONDITION TO SUNDANCE SERVICES, INC.'S ACCEPTANCE OF THE MATERIALS SHIPPED WITH THIS JOB TICKET, OPERATOR/SHIPPER REPRESENTS AND WARRANTS THAT THE WASTE MATERIAL SHIPPED HERewith IS MATERIAL EXEMPT FROM THE RESOURCE, CONSERVATION AND RECOVERY ACT OF 1976, AS AMENDED FROM TIME TO TIME, 40 U.S.C. § 6901, et seq., THE NM HEALTH AND SAF. CODE § 361.001, et seq., AND REGULATIONS RELATED THERETO, BY VIRTUE OF THE EXEMPTION AFFORDED DRILLING FLUIDS, PRODUCED WATERS, AND OTHER WASTE ASSOCIATED WITH THE EXPLORATION, DEVELOPMENT OR PRODUCTION OF CRUDE OIL OR NATURAL GAS OR GEOTHERMAL ENERGY.

ALSO AS A CONDITION TO SUNDANCE SERVICES, INC.'S ACCEPTANCE OF THE MATERIALS SHIPPED WITH THIS JOB TICKET, TRANSPORTER REPRESENTS AND WARRANTS THAT ONLY THE MATERIAL DELIVERED BY OPERATOR/SHIPPER TO TRANSPORTER IS NOW DELIVERED BY TRANSPORTER TO SUNDANCE SERVICES, INC.'S FACILITY FOR DISPOSAL.

THIS WILL CERTIFY that the above Transporter loaded the material represented by this Transporter Statement at the above described location, and that it was tendered by the above described shipper. This will certify that no additional materials were added to this load, and that the material was delivered without incident.

DRIVER: [Signature]

(SIGNATURE)

FACILITY REPRESENTATIVE: [Signature]

(SIGNATURE)

White-Sundance Canary-Sundance Acct#1 Pink-Sundance Acct#2 Gold-Transporter

Revised 12/27/95

EME B-32 Jct. Box Upgrade



After Remediation

(No junction box)