1R - 427 - 202

REPORTS

DATE:

10-18-04

EME K-9-1 Book

IR 0427-202

FINAL

REPORT

RICE OPERATING COMPANY JUNCTION BOX FINAL REPORT

p	y	<u> </u>	·	BOX LOC							
SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNT	Y BOX D	MENSIONS - FI	Depth Depth		
EME	K-9-1 boot	К	9	20\$	37E	Lea		oved 15 ft East			
LAND TYPE: E	BLM	STATE	FEE L/	ANDOWNER	S&W	Cattle C	o. OTHER				
Depth to Groun	ndwater	20	feet	NMOCD	SITE ASSE	ESSMEN	T RANKING S	CORE:	20		
Date Started	7/14/	/2004	Date Co	mpleted	7/19/2004	oc	D Witness	No			
Soil Excavated	36	cubic ya	rds Ex	cavation Le	ngth 3 trenci	<u>hes</u> Wi	dth 3 trenches	Depth	<u>12</u> feet		
Soil Disposed	0	cubic ya	rds Of	fsite Facility	n	/a	Location	n/a	a		
FINAL ANALYTICAL RESULTS: Sample Date											
approved lab	and testing	procedures	s pursuant f	to NMOCD (guidelines.			,	····		
Sample	<u>PID</u>	<u>G</u>	RO	<u>DRO</u>	<u>Chloride</u>		LOCATION	DEPTH (ft)	ppm		
Location	ppm	m(g/kg	mg/kg	mg/kg			6	149		
4-WALL COMP.	0.0	<1	0.0	<10.0	191			7	300		
BOTTOM COMP.	0.0		0.0	38.9	213		vertical at	8	269		
REMED. BACKFILL	0.0	<1	0.0	<10.0	160		junction	9	239		
						•	,	10	239		
General Description	on of Remed	dial Action:	This junction	n box was loca	ted next to			11	180		
a production facility ar	nd it contained	a boot. The	box was exca	avated using a	backhoe while	e		12	149		
chloride field tests and	d PID field scr	eenings were	conducted at	regular interv	als. To 12 ft E	BGS,	Į	6	89		
chloride concentration	s were similar	r to backgrour	nd levels, indi	cative of non-s	aturated		ļ	7	120		
vadose conditions. Al	I PID concent	rations were r	ninimal throu	ghout the 3 de	lineation trend	hes	5 # Fact of	8	149		
and lab results confirm	ned TPH cond	entrations we	li below NMC	CD guidelines	. The		5 ft East of junction	9	239		
excavated soils were I	blended on sit	e and then ba	ckfilled into t	he hole. The c	listurbed			10	119		
surface was seeded w	vith a blend of	native vegeta	tion and is ex	pected to retu	rn to			11	150		
productive capacity at	a normal rate).				\		12	209		
							4-wall comp.	n/a	120		
							bottom comp.	12	240		
enclosures: chloride g	raph, photos,	lab results, P	ID screenings	s, diagram			remed. backfill	n/a	119		
l HEREBY	CERTIFY	THAT THE		TION ABOV			MPLETE TO T	THE BEST OF	MY		
SITE SUPERVISOR	Rob El	am	SIGNATUR	E <u> </u>	ot available		COMPANY Cur	t's Environmenta	ılOdessa, TX		
REPORT ASSEMBLE	D BY	Kristin Farı	is Pope	SIGNAT	URE 4	nirti	n danis	Pope			
n	ATF	10/18/2	2004	т	TTI F		Project Sc	ientist			

undisturbed junction box

7/29/2003

EME K-9-1 Boot

Unit 'K', Sec. 9, T20S, R37E




former junction site; box removed; poly pipeline straight through 6/6/2004



new poly junction 15 ft east of former junction



floor of new junction box





completed junction box

8/2/2004


EME K-9-1 boot

T20S, R37E

Vertical Delineation at Source


	149	300	569	239	239	180	149
Depth high (fit)	9	2	8	6	10	11	12

Groundwater = 20 ft



EME K-9-1 boot


Excavation Plan-View




S E

A D

₩ 0



EASE ROAD



Analytical Report

Prepared for:

Roy Rascon
Rice Operating Co.
122 W. Taylor
Hobbs, NM 88240

Project: K-9-1 Boot
Project Number: None Given
Location: EME

Lab Order Number: 4G16017

Report Date: 07/22/04

Project: K-9-1 Boot

Project Number: None Given Project Manager: Roy Rascon

Fax: (505) 397-1471

Reported: 07/22/04 10:58

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
12' Bottom Composite	4G16017-01	Soil	07/15/04 10:40	07/16/04 16:20
Wall Composite	4G16017-02	Soil	07/15/04 10:40	07/16/04 16:20
Backfill Composite	4G16017-03	Soil	07/15/04 11:30	07/16/04 16:20

Project: K-9-1 Boot Project Number: None Given

Project Manager: Roy Rascon

Fax: (505) 397-1471 Reported: 07/22/04 17:50

Organics by GC **Environmental Lab of Texas**

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
12' Bottom Composite (4G16017-01)	Soil				- -			_ 	
Gasoline Range Organics C6-C12	ND	10.0	mg/kg dry	1	EG41910	07/20/04	07/20/04	EPA 8015M	
Diesel Range Organics >C12-C35	38.9	10.0	n	11		n	ıı	n	
Total Hydrocarbon C6-C35	38.9	10.0	н	II.	Ħ	H	11	n	
Surrogate: 1-Chlorooctane		77.2 %	70-13	30	"	"	"	#	
Surrogate: 1-Chlorooctadecane		71.0 %	70-13	80	"	"	"	"	
Wall Composite (4G16017-02) Soil									
Gasoline Range Organics C6-C12	ND	10.0	mg/kg dry	1 .	EG41910	07/20/04	07/20/04	EPA 8015M	
Diesel Range Organics >C12-C35	ND	10.0	11	U	**	10	11	n	
Total Hydrocarbon C6-C35	ND	10.0	11	17	u	11	11	u	
Surrogate: 1-Chlorooctane		85.6 %	70-13	30	"	"	"	"	
Surrogate: 1-Chlorooctadecane		74.6%	70-13	80	"	"	"	"	
Backfill Composite (4G16017-03) Soi	1								
Gasoline Range Organics C6-C12	ND	10.0	mg/kg dry	1	EG41910	07/20/04	07/20/04	EPA 8015M	
Diesel Range Organics >C12-C35	ND	10.0	ti	#1	11	n	u	"	
Total Hydrocarbon C6-C35	ND	10.0	U	**	11	"	n	u	
Surrogate: 1-Chlorooctane		87.4 %	70-1.	30	"	"	, ,,	"	
Surrogate: 1-Chlorooctadecane		74.8 %	70-13	30	"	"	"	"	

Project: K-9-1 Boot

Project Number: None Given Project Manager: Roy Rascon

Fax: (505) 397-1471

Reported: 07/22/04 10:58

General Chemistry Parameters by EPA / Standard Methods Environmental Lab of Texas

Analyte	Result	Reporting Limit Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
12' Bottom Composite (4G16017-01) So	il		- · · · · · · · · · · · · · · · · · · ·	,	· · · · · · · · · · · · · · · · · · ·			
Chloride	213	20.0 mg/kg Wet	2	EG42015	07/19/04	07/20/04	SW 846 9253	····
% Solids	97.0	%	1	EG42001	07/19/04	07/19/04	% calculation	
Wall Composite (4G16017-02) Soil			•					
% Solids	97.0	%	1	EG42001	07/19/04	07/19/04	% calculation	
Backfill Composite (4G16017-03) Soil								
% Solids	98.0	%	1	EG42001	07/19/04	07/19/04	% calculation	

Project: K-9-1 Boot Project Number: None Given Project Manager: Roy Rascon Fax: (505) 397-1471

Reported:
07/22/04 10:58

Organics by GC - Quality Control Environmental Lab of Texas

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch EG41910 - Solvent Extraction	(GC)									
Blank (EG41910-BLK1)				Prepared	& Analyze	ed: 07/20/	04			
Gasoline Range Organics C6-C12	ND	10.0	mg/kg wet				· · · · · · · · · · · · · · · · · · ·			
Diesel Range Organics >C12-C35	ND	10.0	11							
Total Hydrocarbon C6-C35	ND	10.0	ıı							
Surrogate: 1-Chlorooctane	45.7		mg/kg	50.0		91.4	70-130			
Surrogate: 1-Chlorooctadecane	41.1		ir .	50.0		82.2	70-130			
Blank (EG41910-BLK2)				Prepared:	07/20/04	Analyzed	l: 07/21/04			
Gasoline Range Organics C6-C12	ND	10.0	mg/kg wet				*			
Diesel Range Organics >C12-C35	· ND	10.0	11		٠					
Total Hydrocarbon C6-C35	ND	10.0	n							
Surrogate: 1-Chlorooctane	43.0		mg/kg	50.0		86.0	70-130			
Surrogate: 1-Chlorooctadecane	36.4		" .	50.0	•	72.8	70-130			
LCS (EG41910-BS1)		•		Prepared	& Analyz	ed: 07/20/	04			
Gasoline Range Organics C6-C12	451	10.0	mg/kg wet	500		90.2	75-125	•		
Diesel Range Organics >C12-C35	486	10.0	- n	500		97.2	75-125			
Total Hydrocarbon C6-C35	937	10.0	, , , , , , , , , , , , , , , , , , ,	1000	•	93.7	75-125			
Surrogate: 1-Chlorooctane	49.5		mg/kg	50.0		99.0	70-130			
Surrogate: 1-Chlorooctadecane	37.7		"	50.0		75.4	70-130			
LCS (EG41910-BS2)				Prepared:	07/20/04	Analyzed	1: 07/21/04			
Gasoline Range Organics C6-C12	454	10.0	mg/kg wet	500		90.8	75-125			
Diesel Range Organics >C12-C35	482	10.0	11	500		96.4	75-125			
Total Hydrocarbon C6-C35	936	10.0	" .	1000		93.6	75-125			
Surrogate: I-Chlorooctane	49.4		mg/kg	50.0		98.8	70-130			
Surrogate: 1-Chlorooctadecane	37.9		"	50.0		75.8	70-130			
Calibration Check (EG41910-CCV1)				Prepared	& Analyz	ed: 07/20/	04			
Gasoline Range Organics C6-C12	424	······································	mg/kg	500		84.8	80-120			
Diesel Range Organics >C12-C35	438		**	500		87.6	80-120			
Total Hydrocarbon C6-C35	862		11	1000		86.2	80-120			
Surrogate: 1-Chlorooctane	55.8			50.0		112	70-130			
Surrogate: 1-Chlorooctadecane	38.2		n	50.0		76.4	70-130			

Project: K-9-1 Boot Project Number: None Given Project Manager: Roy Rascon Fax: (505) 397-1471

Reported:

Reported: 07/22/04 10:58

Organics by GC - Quality Control Environmental Lab of Texas

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limít	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch EG41910 - Solvent Extraction	(GC)									
Calibration Check (EG41910-CCV2)	<u>-</u>			Prepared:	07/20/04	Analyzed	l: 07/21/04			
Gasoline Range Organics C6-C12	412		mg/kg	500		82.4	80-120			
Diesel Range Organics >C12-C35	454		11	500		90.8	80-120			
Total Hydrocarbon C6-C35	866		Ħ	1000		86.6	80-120			•
Surrogate: 1-Chlorooctane	55.2		<i>n</i>	50.0		110	70-130			
Surrogate: 1-Chlorooctadecane	40.3		n	50.0		80.6	70-130			
Matrix Spike (EG41910-MS1)	Sou	ırce: 4G160	16-23	Prepared	& Analyz	ed: 07/20/	04			
Gasoline Range Organics C6-C12	448	10.0	mg/kg dry	521	ND	86.0	75-125			
Diesel Range Organics >C12-C35	469	10.0	1)	521	ND	90.0	75-125			
Total Hydrocarbon C6-C35	917	10.0	11	1040	ND	88.2	75-125			
Surrogate: I-Chlorooctane	56.0		mg/kg	50.0		112	70-130			
Surrogate: 1-Chlorooctadecane	36.9		"	50.0		<i>73.8</i>	70-130			
Matrix Spike (EG41910-MS2)	Sou	urce: 4G160	21-05	Prepared:	07/20/04	Analyzed	l: 07/21/04			
Gasoline Range Organics C6-C12	433	10.0	mg/kg dry	515	ND	84.1	75-125			
Diesel Range Organics >C12-C35	513	10.0	11	515	8.10	98.0	75-125			i
Total Hydrocarbon C6-C35	946	10.0	19	1030	ND	91.8	75-125			
Surrogate: 1-Chlorooctane	53.7		mg/kg	50.0		107	70-130			
Surrogate: 1-Chlorooctadecane	41.2		"	50.0		82.4	70-130			
Matrix Spike Dup (EG41910-MSD1)	So	urce: 4G160	16-23	Prepared:	: 07/20/04	Analyzec	i: 07/22/04			
Gasoline Range Organics C6-C12	456	10.0	mg/kg dry	521	ND	87.5	75-125	1.77	20	
Diesel Range Organics >C12-C35	487	10.0	n	521	ND	93.5	75-125	3.77	20	
Total Hydrocarbon C6-C35	943	10.0	ır	1040	ND	90.7	75-125	2.80.	20	
Surrogate: 1-Chlorooctane	51.6		mg/kg	50.0		103	70-130			
Surrogate: 1-Chlorooctadecane	41.9		"	50.0		83.8	70-130			
Matrix Spike Dup (EG41910-MSD2)	So	urce: 4G160	21-05	Prepared	: 07/20/04	Analyzed	i: 07/21/04			
Gasoline Range Organics C6-C12	446	10.0	mg/kg dry	515	ND	86.6	75-125	2.96	20	
Diesel Range Organics >C12-C35	471	10.0	n	515	8.10	89.9	75-125	8.54	20	
Total Hydrocarbon C6-C35	917	10.0	"	1030	ND	89.0	75-125	3.11	20	
Surrogate: 1-Chlorooctane	54.6		mg/kg	50.0		109	70-130			
Surrogate: 1-Chlorooctadecane	37.4		#	50.0		<i>74.8</i>	70-130			

Project: K-9-1 Boot

Project Number: None Given Project Manager: Roy Rascon

Fax: (505) 397-1471

Reported: 07/22/04 10:58

General Chemistry Parameters by EPA / Standard Methods - Quality Control Environmental Lab of Texas

		Spike	Spike Source				RPD		
Analyte	Result	Limit Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch EG42001 - General Preparation	(Prep)								
Blank (EG42001-BLK1)			Prepared	& Analyz	ed: 07/19/	04			
% Solids	100	%							
Duplicate (EG42001-DUP1)	Sou	rce: 4G16015-03	Prepared	& Analyz	ed: 07/19/	04			
% Solids	89.0	%		89.0			0.00	20	
Batch EG42015 - Water Extraction									······
Blank (EG42015-BLK1)			Prepared:	07/19/04	Analyzed	: 07/20/04			
Chloride	ND	20.0 mg/kg Wet							
Matrix Spike (EG42015-MS1)	Sou	rce: 4G16016-22	Prepared:	07/19/04	Analyzed	: 07/20/04			
Chloride	532	20.0 mg/kg Wet	500	21.3	102	80-120			
Matrix Spike Dup (EG42015-MSD1)	Sou	rce: 4G16016-22	Prepared:	07/19/04	Analyzed	: 07/20/04			
Chloride -	521	20.0 mg/kg Wet	500	21.3	99.9	80-120	2.09	20	
Reference (EG42015-SRM1)			Prepared:	07/19/04	Analyzed	: 07/20/04			
Chloride	5000	mg/kg	5000		100	80-120			

Project: K-9-1 Boot Project Number: None Given Project Manager: Roy Rascon Fax: (505) 397-1471 Reported: 07/22/04 10:58

Notes and Definitions

Analyte DETECTED DET

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

Sample results reported on a dry weight basis dry

RPD Relative Percent Difference

LCS Laboratory Control Spike

MS Matrix Spike

Dup Duplicate

Report Approved By:

Raland K. Tuttle, QA Officer

Celey D. Keene, Lab Director, Org. Tech Director

Jeanne Mc Murrey, Inorg. Tech Director

James L. Hawkins, Chemist/Geologist

Sara Molina, Chemist

Sandra Biezugbe, Lab Tech.

This material is intended only for the use of the individual (s) or entity to whom it is addressed, and may contain information that is privileged and confidential.

If you have received this material in error, please notify us immediately at 432-563-1800.

Environmental Lab of Texas, Inc.

Odessa, Texas 79763 12600 West I-20 East

Phone: 915-563-1800 Fax: 915-563-1713

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

Project Name:

Project #:

Roy Rascon

Project Manager:

Operating Company Name RICE

Taylor city/State/Zip: Hobbs, NM Company Address: 123 W.

Telephone No: (SOS) 393-9174

Sampler Signature:

397-147

EME

Project Loc:

PO #:

TAT bisbnst2 RUSH TAT (Pre-Schedule) Гелирага**ште** Upon Receipt Sample Containers Infact? Analyze For aboratory Comments BTEX 8021B/5030 Metals: As Ag Ba Cd Cr Pb Hg Se TOLP: TPH 8015M GRO/DRO TOTAL 8001/2001 XT H9T 27004 1050 1.814 H9T 14. W Cl as per attached fax 7.27.4 DE V RACE OD SOFT Ofner (specify): Date 1-16 Sindge Other (Specify) os²H HCI HNO; No. of Containers * acld 10:46 A 11: 30 A 10:40 A Time Sampled 7-15-14 7-15-04 7-15.04 Received by: Date Sampled 7-16/4 16:20 7-15-04 4:55 Composite Composite Wall Composite FIELD CODE 12' Bottom Back A: 11 8015 700 ٦ Special Instructions: .AB # (lab use only)

RICE Operating Company

122 West Taylor Habbs, NM 88240 Phone: (505) 393-9174 Faz (505) 397-1471

RALAND K. Tuttle	FROM Ray P. RASCON
FAX NUMBER	DATE
432-563-1713	7-27-03
COMPANY:	TOTAL NO. OF PAGE INCLUDING COVER
ELOT	· /
RE	
LAG ORDER NO. # 4G16017	
Please Run a Cl test on	the wall comp. of
on the Backfill Comp.	

IF YOU DO NOT RECEIVE ALL PAGES INCLUDED, PLEASE CALL THE OFFICE PHONE NUMBER LISTED AT TITETOP OF THIS PAGE-THANK YOU

Environmental Lab of Texas Variance / Corrective Action Report – Sample Log-In

Client: Rice Operating Co.					
Olient: Rice Operating Co. Date/Time: 07-16-04 @ 1515					
Order#: 4G16018					,
Initials:					
Sample Receipt	Chackli	et			
Temperature of container/cooler?	(Ce)	No	11.60	С	
Shipping container/cooler in good condition?	(Yes)	No	4,0		
Custody Seals intact on shipping container/cooler?	Yes	No	(Ngt preser	-	
Custody Seals intact on sample bottles?	Yes	No	Not preser		
Chain of custody present?		No	Quot preser	10	
Sample Instructions complete on Chain of Custody?	Yes				
	(Pes)	No	· · · · · · · · · · · · · · · · · · ·		
Chain of Custody signed when relinquished and received?	(65)	No			
Chain of custody agrees with sample label(s)	CES	No			
Container labels legible and intact?	Yes	No			
Sample Matrix and properties same as on chain of custody?	Yes	No			
Samples in proper container/bottle?	res	No			
Samples properly preserved?	(Tes)	No			
Sample bottles intact?	(Yes)	No			
Preservations documented on Chain of Custody?	(Tes)	No_			
Containers documented on Chain of Custody?	(Yes)	No			
Sufficient sample amount for indicated test?	TES	No			
All samples received within sufficient hold time?	(Yes)	No			
VOC samples have zero headspace?	Yes	No_	Not Applicat	ole	
Other observations:					
Variance Docum	entatio	n·			
Contact Person: Date/Time:			Contacted h	υV.	
			Comacieur	уу	
Regarding:					
Corrective Action Taken:					
					
				 -	
					
•					



Analytical Report

Prepared for:

Roy Rascon
Rice Operating Co.
122 W. Taylor
Hobbs, NM 88240

Project: K-9-1 Boot
Project Number: None Given
Location: EME

Lab Order Number: 4G16017

Report Date: 07/28/04

Project: K-9-1 Boot
Project Number: None Given
Project Manager: Roy Rascon

Fax: (505) 397-1471

Reported:

Reported: 07/28/04 12:27

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
Wall Composite	4G16017-02	Soil	07/15/04 10:40	07/16/04 16:20
Backfill Composite	4G16017-03	Soil	07/15/04 11:30	07/16/04 16:20

Project: K-9-1 Boot
Project Number: None Given
Project Manager: Roy Rascon

Fax: (505) 397-1471

Reported:
07/28/04 12:27

General Chemistry Parameters by EPA / Standard Methods

Environmental Lab of Texas

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
Wall Composite (4G16017-02) Soil									
Chloride	191	20.0	mg/kg Wet	2	EG42710	07/27/04	07/27/04	SW 846 9253	
Backfill Composite (4G16017-03) Soil									
Chloride	160	20.0 1	mg/kg Wet	2	EG42710	07/27/04	07/27/04	SW 846 9253	

Project: K-9-1 Boot

Project Number: None Given Project Manager: Roy Rascon

Fax: (505) 397-1471

Reported: 07/28/04 12:27

General Chemistry Parameters by EPA / Standard Methods - Quality Control Environmental Lab of Texas

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch EG42710 - Water Extraction										
Blank (EG42710-BLK1)				Prepared &	k Analyzed:	07/27/04				
Chloride	ND	20.0	mg/kg Wet							
Matrix Spike (EG42710-MS1)	Sou	rce: 4G27001	1-01	Prepared &	k Analyzed:	07/27/04				
Chloride	532	20.0	mg/kg Wet	500	85.1	89.4	80-120			
Matrix Spike Dup (EG42710-MSD1)	Source: 4G27001-01		Prepared & Analyzed: 07/27/04							
Chloride	542	20.0	mg/kg Wet	500	85.1	91.4	80-120	1.86	20	
Reference (EG42710-SRM1)	Prepared & Analyzed: 07/27/04									
Chloride	4890		mg/kg	5000		97.8	80-120			

Rice Operating Co.Project:K-9-1 BootFax: (505) 397-1471122 W. TaylorProject Number:None GivenReported:Hobbs NM, 88240Project Manager:Roy Rascon07/28/04 12:27

Notes and Definitions

Analyte DETECTED DET Analyte NOT DETECTED at or above the reporting limit ND NR Not Reported dry Sample results reported on a dry weight basis Relative Percent Difference RPD Laboratory Control Spike LCS Matrix Spike MS Duplicate Dup

Report Approved By: __ Cley D. Keene

Date:

Raland K. Tuttle, QA Officer Celey D. Keene, Lab Director, Org. Tech Director Jeanne Mc Murrey, Inorg. Tech Director

James L. Hawkins, Chemist/Geologist Sara Molina, Chemist Sandra Biezugbe, Lab Tech.

This material is intended only for the use of the individual (s) or entity to whom it is addressed, and may contain information that is privileged and confidential.

If you have received this material in error, please notify us immediately at 432-563-1800.

Project: K-9-1 Boot
Project Number: None Given
Project Manager: Roy Rascon

Fax: (505) 397-1471

Reported:
07/28/04 12:27

Environmental Lab of Texas

The results in this report apply to the samples analyzed in accordance with the samples received in the laboratory. This analytical report must be reproduced in its entirety, with written approval of Environmental Lab of Texas.

Page 5 of 5

KILL UPERATING COMPANY

122 WEST TAYLOR

HOBBS, NEW MEXICO 88240

PHONE: (505) 393-9174 FAX: (505) 397-1471

VOC FIELD TEST REPORT FORM

MINI RAE PLUS CLASSIC PHOTOIONIZATION GAS DETECTOR

MODEL NO: PGM 761S

CALIBRATION GAS

GAS COMPOSITION: ISOBUTYLENE

AIR

LOTNO: 03-2475

EXP. DATE: 10-19-05

METER READING

ACCURACY: ____/00.°

SERIAL NO: 104412 104550

100 PPM

BALANCE

FILL DATE: 4-19-04

ACCURACY: \$ 270

SYSTEM	JUNCTION	UNII	SECTION	TOWNSEIP	RANGE
EME	K-9-1	K.	9	20.5	37€

. •	The second secon	***	a a a a a a granda an an a a a a a a a a a a a a a a a
SAMPLE.	PID RESULT	SAMPLE	PID RESULT
North Wall Comp	2.2		
South Wall Comp	1.2	Supplied to the supplied to th	A CONTRACTOR OF THE CONTRACTOR
East Wall Comp	1.1		
West Wall Comp	0		
Botton Comp	0		
Wall Comp.	0		
Backfill Comp	0		
,			

I certify that I have calibrated the above instrument in accordance to the manufacture operation manual.

Rob Elam Signature

7-15-04