

1R - 427 - 60

REPORTS

DATE:

3-15-2002

1R0427-60

FINAL REPORT

RICE OPERATING COMPANY JUNCTION BOX FINAL REPORT

BOX LOCATION

SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNTY	BOX DIMENSIONS - FEET		
EME	M-34	M	34	19S	37E	LEA	Length 12	Width 10	Depth 6

LAND TYPE: BLM _____ STATE _____ FEE LANDOWNER _____ COY DOYAL _____ OTHER _____

Depth to Groundwater <50 feet NMOC SITE ASSESSMENT RANKING SCORE: 20

Date Started 3/1/2002 Date Completed 3/5/2002 OCD Witness NO

Soil Excavated 160 cubic yards Excavation Length 25 Width 20 Depth 9' feet

Soil Disposed 132 cubic yards Offsite Facility J&L LANDFARM Location MONUMENT

FINAL ANALYTICAL RESULTS: Sample Date 3/4/2002 Sample Depth 9'

Procure 5-point composite sample of bottom and 4-point composite sample of sidewalls. TPH,
BTEX and Chloride laboratory test results completed by using an approved lab and testing
procedures pursuant to NMOC guidelines.

Sample Location	Benzene mg/kg	Toluene mg/kg	Ethyl Benzene mg/kg	Total Xylenes mg/kg	GRO mg/kg	DRO mg/kg	Chlorides mg/kg
SIDEWALLS	<0.025	<0.025	<0.025	<0.025	<10	22.7	414
BOTTOM	<0.025	<0.025	<0.025	<0.025	<10	42.8	606
Boring @ 35'	<0.025	<0.025	<0.025	<0.025	<10	<10	71

General Description of Remedial Action: Delineated vertical and lateral extent.

Vertical delineation found TPH clean at 9' bgs. A soil boring found chlorides declined

from 950 ppm @ 20' to 71 ppm @ 35' bgs. This demonstrates that impact stopped before reaching groundwater. A compacted clay barrier and water tight junction box was installed

and backfilled. High impacted soil was hauled to a permitted disposal facility. Natural attenuation will remediate the remaining hydrocarbon.


CHLORIDE FIELD TESTS

LOCATION	DEPTH	mg/kg
SIDEWALLS	8'	300
BOTTOM	9'	500
Vertical Trench	15'	2300
Soil Boring	10'	170
	15'	430
	20'	950
	23'	540
	26'	520
	32'	160
	35'	120

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY
KNOWLEDGE AND BELIEF.

DATE March 15, 2002

PRINTED NAME D. E. Anderson

SIGNATURE 

TITLE Project Leader - Environmental

DRILLING LOG		Site Name/Location		Well No.		Date Drilled:		Driller:		Logged by:	
RICE Operating Company 122 West Taylor Hobbs, New Mexico 88240 Phone: (505) 393-9174 Fax: (505) 397-1471		Jct. Box M-34 20-T22S-R37E Eunice Monument Eumont SWD System Lea County, NM		N/A		2/28/02		Eades		F. Root	
				Well Depth: N/A		Boring Depth: 35'		Well Material: N/A		Construction:	
				Casing Length: N/A		Boring Diameter: 4.5"		Casing Size: N/A		Plugged boring	
				Screen Length: N/A		Drilling Method: Air Rotary		Slot Size: N/A		w/ 15' bentonite, water & backfill	
TEST											
DEPTH	SUBSURFACE LITHOLOGY	SAMPLE TYPE	(ppm)	REMARKS	Boring						
0	Ground surface		CF								
1	Top Soil										
2	Caliche										
3											
4											
5											
6											
7											
8											
9											
10		Grab	170								
11											
12											
13											
14											
15		Grab	430								
16											
17											
18											
19											
20	Sandstone	Grab	950								
21	Sand										
22											
23		Grab	540								
24											
25											
26		Grab	520								
27											
28											
29											
30		Grab	340								
31	Sandstone										
32	Sand and sandstone stringers	Grab	160								
33											
34											
35		Grab	120								

ANALYTICAL REPORT

Prepared for:

DONNIE ANDERSON
RICE OPERATING CORP.
122 WEST TAYLOR
HOBBS, NM 88242

Project: Jct M-34 box Upgrade

Order#: G0202741

Report Date: 03/07/2002

Certificates

US EPA Laboratory Code TX00158

ENVIRONMENTAL LAB OF TEXAS

SAMPLE WORK LIST

RICE OPERATING CORP.
122 WEST TAYLOR

HOBBS, NM 88242

Order#: G0202741
Project: Soil bore @ 35'
bgs
Project Name: Jct M-34 box Upgrade
Location: EME

The samples listed below were submitted to Environmental Lab of Texas and were received under chain of custody. Environmental Lab of Texas makes no representation or certification as to the method of sample collection, sample identification, or transportation/handling procedures used prior to the receipt of samples by Environmental Lab of Texas.

			Date / Time	Date / Time		
0202741-01	Soil bore @ 35' bgs	SOIL		3/5/02	4 oz Glass	ice
				17:00		
	<u>Lab Testing:</u>	Rejected: No	Temp:	2C		
	8015M TPH GRO/DRO					
	8021B/5030 BTEX					
	Chloride					

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

DONNIE ANDERSON
RICE OPERATING CORP.
122 WEST TAYLOR
HOBBS, NM 88242

Order#: G0202741
Project: Soil bore @ 35' bgs
Project Name: Jct M-34 box Upgrade
Location: EME

Lab ID: 0202741-01
Sample ID: Soil bore @ 35' bgs

8015M TPH GRO/DRO


Method	Date	Date	Sample	Dilution		
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>	<u>Analyst</u>	<u>Method</u>
0000785-02		3/6/02 13:46	1	1	CK	8015

Parameter	Result mg/kg	RL
GRO, C6-C12	<10	10.0
DRO, >C12-C28	<10	10.0

8021B/5030 BTEX

Method	Date	Date	Sample	Dilution		
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>	<u>Analyst</u>	<u>Method</u>
0000783-02		3/6/02 14:12	1	1	CK	8021B

Parameter	Result µg/kg	RL
Benzene	<25	25.0
Ethylbenzene	<25	25.0
Toluene	<25	25.0
p/m-Xylene	<25	25.0
o-Xylene	<25	25.0

Approval:  3-07-02
Raland K. Tuttle, Lab Director, QA Officer
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Irene Perry, QA Assistant
Sandra Biezugbe, Lab Tech.
Curt Cowdrey, Lab Tech.
Sara Molina, Lab Tech.

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

DONNIE ANDERSON
RICE OPERATING CORP.
122 WEST TAYLOR
HOBBS, NM 88242

Order#: G0202741
Project: Soil bore @ 35' bgs
Project Name: Jet M-34 box Upgrade
Location: EME

Lab ID: 0202741-01
Sample ID: Soil bore @ 35' bgs

Test Parameters

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Dilution Factor</u>	<u>RL</u>	<u>Method</u>	<u>Date Analyzed</u>	<u>Analyst</u>
Chloride	71.0	mg/kg	1	5.0	9253	3/6/02	SB

Approval:

Raland K. Tuttle

3-07-02

Raland K. Tuttle, Lab Director, QA Officer
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Irene Perry, QA Assistant
Sandra Biezugbe, Lab Tech.
Curt Cowdrey, Lab Tech.
Sara Molina, Lab Tech.

Date

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

8015M TPH GRO/DRO

Order#: G0202741

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0000785-02			<10		
DRO, >C12-C28-mg/kg	0000785-02			<10		
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0202740-01	0	476	447	93.9%	
DRO, >C12-C28-mg/kg	0202740-01	0	476	563	118.3%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0202740-01	0	476	424	89.1%	5.3%
DRO, >C12-C28-mg/kg	0202740-01	0	476	506	106.3%	10.7%
SRM	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0000785-05		500	441	88.2%	0.0%
DRO, >C12-C28-mg/kg	0000785-05		500	524	104.8%	0.0%

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

8021B/5030 BTEX

Order#: G0202741

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-μg/kg	0000783-02			<25		
Ethylbenzene-μg/kg	0000783-02			<25		
Toluene-μg/kg	0000783-02			<25		
p/m-Xylene-μg/kg	0000783-02			<25		
o-Xylene-μg/kg	0000783-02			<25		
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-μg/kg	0202728-02	0	100	112	112.0%	
Ethylbenzene-μg/kg	0202728-02	0	100	111	111.0%	
Toluene-μg/kg	0202728-02	0	100	113	113.0%	
p/m-Xylene-μg/kg	0202728-02	0	200	230	115.0%	
o-Xylene-μg/kg	0202728-02	0	100	112	112.0%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-μg/kg	0202728-02	112	100	113	113.0%	0.9%
Ethylbenzene-μg/kg	0202728-02	111	100	112	112.0%	0.9%
Toluene-μg/kg	0202728-02	113	100	113	113.0%	0.0%
p/m-Xylene-μg/kg	0202728-02	230	200	228	114.0%	0.9%
o-Xylene-μg/kg	0202728-02	112	100	114	114.0%	1.8%
SRM	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-μg/kg	0000783-05		100	112	112.0%	0.0%
Ethylbenzene-μg/kg	0000783-05		100	111	111.0%	0.0%
Toluene-μg/kg	0000783-05		100	114	114.0%	0.0%
p/m-Xylene-μg/kg	0000783-05		200	229	114.5%	0.0%
o-Xylene-μg/kg	0000783-05		100	112	112.0%	0.0%

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

Test Parameters

Order#: G0202741

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0000787-01			<5.00		
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0202739-01	248	667	910	99.3%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0202739-01	248	667	922	101.0%	1.3%
SRM	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0000787-04		5000	5050	101.0%	0.0%

12500 West I-20 East
Odessa, Texas 79763

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

Project Manager: DONNIE ANDERSON

Company Name RICE OPERATING COMPANY

Company Address: 122 W. TAYLOR

City/State/Zip: HOBBS, NEW MEXICO, 88240

Telephone No: (505) 393-9174

Fax No: (505) 397-1471

Sampler Signature:

Project Name: lot M-34 box upgrade

Project #: Soil bore @ 35' bgs

Project Loc: CME

PO #:

[illegible]

ANALYTICAL REPORT

Prepared for:

DEREK ROBINSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Project: Rice M-34
Order#: G0202728
Report Date: 03/06/2002

Certificates

US EPA Laboratory Code TX00158

ENVIRONMENTAL LAB OF TEXAS

SAMPLE WORK LIST

RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768
366-0804

Order#: G0202728
Project:
Project Name: Rice
Location: M-34

The samples listed below were submitted to Environmental Lab of Texas and were received under chain of custody. Environmental Lab of Texas makes no representation or certification as to the method of sample collection, sample identification, or transportation/handling procedures used prior to the receipt of samples by Environmental Lab of Texas.

<u>Lab ID:</u>	<u>Sample :</u>	<u>Matrix:</u>	<u>Date / Time</u> <u>Collected</u>	<u>Date / Time</u> <u>Received</u>	<u>Container</u>	<u>Preservative</u>
0202728-01	5 pt. Bottom Comp. @ 9'	SOIL	03/04/2002 15:00	03/05/2002 8:20	4 oz glass	Ice
<u>Lab Testing:</u>		Rejected: No	Temp: 14.0 C			
8015M TPH GRO/DRO						
8021B/5030 BTEX						
Chloride						
0202728-02	4 pt. Wall Comp. @ 8'	SOIL	03/04/2002 13:00	03/05/2002 8:20	4 oz glass	Ice
<u>Lab Testing:</u>		Rejected: No	Temp: 14.0 C			
8015M TPH GRO/DRO						
8021B/5030 BTEX						
Chloride						

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

DEREK ROBINSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0202728
Project:
Project Name: Rice
Location: M-34

Lab ID: 0202728-01
Sample ID: 5 pt. Bottom Comp. @ 9'

8015M TPH GRO/DRO

Method	Date	Date	Sample	Dilution	Analyst	Method
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>		
0000776-02		03/05/2002 21:30	1	1	CK	8015

Parameter	Result mg/kg	RL
GRO, C6-C12	<10	10.0
DRO, >C12-C28	42.8	10.0

8021B/5030 BTEX

Method	Date	Date	Sample	Dilution	Analyst	Method
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>		
0000783-02		03/05/2002 12:09	1	1	CK	8021B

Parameter	Result µg/kg	RL
Benzene	<25	25.0
Ethylbenzene	<25	25.0
Toluene	<25	25.0
p/m-Xylene	<25	25.0
o-Xylene	<25	25.0

Lab ID: 0202728-02
Sample ID: 4 pt. Wall Comp. @ 8'

8015M TPH GRO/DRO

Method	Date	Date	Sample	Dilution	Analyst	Method
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>		
0000776-02		03/05/2002 21:42	1	1	CK	8015

Parameter	Result mg/kg	RL
GRO, C6-C12	<10	10.0
DRO, >C12-C28	22.7	10.0

DL = Diluted out N/A = Not Applicable RL = Reporting Limit

Page 1 of 2

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

DEREK ROBINSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0202728
Project:
Project Name: Rice
Location: M-34

Lab ID: 0202728-02
Sample ID: 4 pt. Wall Comp. @ 8'

8021B/5030 BTEX

Method	Date	Date	Sample	Dilution	Analyst	Method
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>		
0000783-02		03/05/102 20:32	1	1	CK	8021B

Parameter	Result µg/kg	RL
Benzene	<25	25.0
Ethylbenzene	<25	25.0
Toluene	<25	25.0
p/m-Xylene	<25	25.0
o-Xylene	<25	25.0

Approval: Raland K. Tuttle 3-06-02
Raland K. Tuttle, Lab Director, QA Officer Date
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Irene Perry, QA Assistant
Sandra Biezugbe, Lab Tech.
Curt Cowdrey, Lab Tech.
Sara Molina, Lab Tech.

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

DEREK ROBINSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0202728
Project:
Project Name: Rice
Location: M-34

Lab ID: 0202728-01
Sample ID: 5 pt. Bottom Comp. @ 9'

Test Parameters

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Dilution Factor</u>	<u>RL</u>	<u>Method</u>	<u>Date Analyzed</u>	<u>Analyst</u>
Chloride	606	mg/kg	1	5.0	9253	03/05/2002	CC

Lab ID: 0202728-02
Sample ID: 4 pt. Wall Comp. @ 8'

Test Parameters

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Dilution Factor</u>	<u>RL</u>	<u>Method</u>	<u>Date Analyzed</u>	<u>Analyst</u>
Chloride	414	mg/kg	1	5.0	9253	03/05/2002	CC

Approval:

Raland K. Tuttle
Raland K. Tuttle, Lab Director, QA Officer
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Irene Perry, QA Assistant
Sandra Biezugbe, Lab Tech.
Curt Cowdrey, Lab Tech.
Sara Molina, Lab Tech.

3-06-02

Date

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

8015M TPH GRO/DRO

Order#: G0202728

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0000776-02			<10		
DRO, >C12-C28-mg/kg	0000776-02			<10		
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0202728-02	0	476	489	102.7%	
DRO, >C12-C28-mg/kg	0202728-02	22.7	476	564	113.7%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0202728-02	0	476	480	100.8%	1.9%
DRO, >C12-C28-mg/kg	0202728-02	22.7	476	553	111.4%	2.0%
SRM	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
GRO, C6-C12-mg/kg	0000776-05		500	452	90.4%	0.0%
DRO, >C12-C28-mg/kg	0000776-05		500	527	105.4%	0.0%

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

8021B/5030 BTEX

Order#: G0202728

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-µg/kg	0000783-02			<25		
Ethylbenzene-µg/kg	0000783-02			<25		
Toluene-µg/kg	0000783-02			<25		
p/m-Xylene-µg/kg	0000783-02			<25		
o-Xylene-µg/kg	0000783-02			<25		
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-µg/kg	0202728-02	0	100	112	112.%	
Ethylbenzene-µg/kg	0202728-02	0	100	111	111.%	
Toluene-µg/kg	0202728-02	0	100	113	113.%	
p/m-Xylene-µg/kg	0202728-02	0	200	230	115.%	
o-Xylene-µg/kg	0202728-02	0	100	112	112.%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-µg/kg	0202728-02	0	100	113	113.%	0.9%
Ethylbenzene-µg/kg	0202728-02	0	100	112	112.%	0.9%
Toluene-µg/kg	0202728-02	0	100	113	113.%	0.9%
p/m-Xylene-µg/kg	0202728-02	0	200	228	114.%	0.9%
o-Xylene-µg/kg	0202728-02	0	100	114	114.%	1.8%
SRM	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-µg/kg	0000783-05		100	112	112.%	0.9%
Ethylbenzene-µg/kg	0000783-05		100	111	111.%	0.9%
Toluene-µg/kg	0000783-05		100	114	114.%	0.9%
p/m-Xylene-µg/kg	0000783-05		200	229	114.5%	0.9%
o-Xylene-µg/kg	0000783-05		100	112	112.%	0.9%

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

Test Parameters

Order#: G0202728

BLANK	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0000769-01			< 5.0		
CONTROL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0000769-02		5000	5140	102.8%	
MS	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0202723-01	786	625	1396	97.6%	
MSD	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg	0202723-01	786	625	1374	94.1%	1.6%

12600 West I-20 East
Odessa, Texas 79763

Phone: 915-563-1800
Fax: 915-563-1713

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

Project Manager: Derek Robinson

Company Name RE Environmental

Company Address:

City/State/Zip:

Telephone No:

Sampler Signature:

Fax No:

Quint Robinson

LAB # (lab use only)						FIELD CODE		Date Sampled	Time Sampled	No. of Containers	Preservative								Matrix				TCLP:	TOTAL:		Analyze For:										
											HNO ₃	HCl	NaOH	H ₂ SO ₄	None	Other (Specify)	Water	Sludge	Soil	Other (Specify)	TDS CL/SAR / EC	TPH 418.1	TPH TX 1005/1006	TPH 8015M GRO/DRO	Metals: As Ag Ba Cd Cr Pb Hg Se	Volatiles	Semivolatiles	BTEX 8021B/5030								
0202728-01						5 ft. Bottom Comp. @ 9'	3-4-02	3:00 pm	1	☒								☒				☒		☒												RUSH TAT (Pre-Schedule)
02						4 ft. Wall comp @ 8'	3-4-02	1:00 pm	1	☒												☒		☒												
Special Instructions: Fax Results to Donnie Anderson & Derek Robinson.																																				
Relinquished by:						Date		Time		Received by:		Date		Time		Sample Containers intact? Temperature Upon Receipt Laboratory Comments:																				
Carter Elen						3-5-2		0820		Donnie Anderson		3-5-2		0820		Y N 14.0°C																				



J & L LANDFARM, INC.

P.O. BOX 356
HOBBS, NEW MEXICO 88241-0356
PHONE (505) 393-9697 • PERMIT # NM-01-0023

0349

Generator/Company RICE OPERATING

Authorized Representative DONNIE ANDERSON

Originating Site M-34 JUNCTION
sec. 34 19S 37E

Transporter REE CONSTRUCTION, YARDS

Authorized Representative Don Palmer

Brief Description of Material NON-HAZ SOIL

Estimated Volume 132 YARDS

TPH SEE TEST

BE-TEX 11 11

CERTIFICATE OF CHEMICAL ANALYSIS (if required) N/A

Don M. Roberts
FACILITY AUTHORIZED REPRESENTATIVE

MARCH 5 2002
DATE

EME M-34 Junction Box Upgrade



Remediation with New Plumbing