

1R - 426-61

REPORTS


DATE:

1/11/2002

IR-426-61

FINAL REPORT

BOX LOCATION

DATE 01/11/2002 PRINTED NAME D. E. Anderson
SIGNATURE  TITLE Project Leader - Environmental

**ANALYTICAL RESULTS FOR
RICE OPERATING CO.
ATTN: CHRIS RODRIGUEZ
122 W. TAYLOR
HOBBS, NM 88240
FAX TO: (505) 397-1471**

Receiving Date: 01/02/02
Reporting Date: 01/04/02
Project Number: B-22-3
Project Name: WALL & BOTTOM COMPOSITES
Project Location: B-D

Sampling Date: 12/28/01
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: AH
Analyzed By: BC/AH

LAB NUMBER	SAMPLE ID	GRO (C ₆ -C ₁₀) (mg/Kg)	DRO (>C ₁₀ -C ₂₈) (mg/Kg)	Cl* (mg/Kg)
ANALYSIS DATE		01/02/02	01/02/02	01/03/02
H6384-1	WALL COMPOSITE	<50	98.0	112
H6384-2	BOTTOM COMPOSITE	<50	75.0	192
Quality Control		726	666	1050
True Value QC		800	800	1000
% Recovery		90.8	83.3	105
Relative Percent Difference		3.9	1.1	3.0

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Cl⁻: Std. Methods 4500-Cl⁻B

*Analyses performed on 1:4 w:v aqueous extracts.

Chemist

Date _____

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable services. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



ARDINAL LABORATORIES

PHONE (815) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2328 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
RICE OPERATING CO.
ATTN: CHRIS RODRIGUEZ
122 W. TAYLOR
HOBBS, NM 88240
FAX TO: (505) 397-1471

Receiving Date: 01/02/02
Reporting Date: 01/04/02
Project Number: B-22-3
Project Name: WALL & BOTTOM COMPOSITES
Project Location: B-D

Sampling Date: 12/28/01
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: AH
Analyzed By: BC

LAB NUMBER	SAMPLE ID	BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL BENZENE (mg/Kg)	TOTAL XYLENES (mg/Kg)
ANALYSIS DATE		01/02/02	01/02/02	01/02/02	01/02/02
H8384-1	WALL COMPOSITE	<0.005	<0.005	<0.005	<0.015
H8384-2	BOTTOM COMPOSITE	<0.005	0.012	0.008	0.020
Quality Control		0.095	0.096	0.101	0.297
True Value QC		0.100	0.100	0.100	0.300
% Recovery		95.1	98.0	101	98.8
Relative Percent Difference		11.3	5.2	5.7	4.8

METHOD: EPA SW-846 8260

Burford J. Cash
Chemist

1/4/02
Date

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

H6384B.XLS

ANALYSIS REQUEST

Page of

2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240
(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

[illegible]

Cardinal cannot accept verbal changes. Please fax written changes to 815-673-7020.