

2R - 15

REPORTS

DATE:

11/18/1994

United States Department of the Interior
Bureau of Land Management
Roswell District

Hazardous Materials Site Report

I. Site Inventory - to be completed by field personnel. (Do not take samples or try to pry open containers). Fill out this form and report incident.

Report Completed by: Joe TORRES
Title: HAZMAT Coord. Date: 4/26/94 Time: 9AM (appr)

Legal Land Description: sec S05E34 T. 22S R. 23E
Resource Area: Carlsbad County: Eddy SACOHU1ST
ICE
NM 7194

Operator (if known): VATES Petro / Jim's Water Service
Address: 105 S. 4th St. ARTESIA 88210 (P.O. BOX 848)
Phone Number: 748-1471 (ARTESIA, NM 88210)
Contact Person: DARRELL ATKINS (MID EAY CLARK - 505-748-1352)

Description of Site: (CAUTION: DO NOT CONTACT MATERIAL OR GET CLOSE ENOUGH TO INJURE YOURSELF).

1. Nature of material, i.e., solid, liquid, color, odor, or odd appearance: Produced Water, BAD ODOR (H₂S)

2. Type or types of containers (if any). Give size, shape, color, material, and whether horizontal or vertical: TRUCK, TANKER

3. Condition of container. Give any evidence of leakage or damage to container: NONE

4. Company names, labels, warning signs, or serial numbers on containers: (warning: read labels from a safe distance with binoculars).

NO LABELS - Jim WATER SERVICE on truck -

5. Approximate size of area affected:
Unknown

6. Location of site - on a hill, in gully or arroyo, along road, etc.: Went into a cave or sink hole -

7. Type of site - dump, abandoned mine complex, oil well, etc.: illegal dumping of produced water into a cave near an oil well

8. Evidence of dead or damaged vegetation or animals. Give type of vegetation or animal: TWO yuccas - Run over

II. Evaluation of Hazardous Materials Site.

Site reported to District Office:

Date: 4-26-94 Time: 8:45A. By: Gene Hunt PET-BLM

Site reported to State Office:

Date: 4-26-94 Time: 10AM By: Joe Torres, LLMC-BLM-064

Ranking of Site According to EPA System:

Major site (priority list): Number of Points: _____

Position on National Priorities List: _____

Minor site (operator cleanup): Number of Points: _____

Position on National Priorities List: _____

Summary of EPA Investigation and Evaluation of Site:

Identification of material(s): Produced Water (foul smelling)

Land Status: Fed Amins, Fed Surface -

Liabilities and remedies: _____

Abatements suggested: _____

Summary of Action:

Remedial Action (action taken to correct spill, leakage, or contamination): Rancher stopped trucker from dumping
Sampled truck water-well @ residence, Spring

Initiation date: 4-26-94 Completion date: _____

BLM Personnel Assigned for Monitoring Remedial Action:

III. Additional Information Pertaining to Site:



