

3R - 170

## APPROVALS

YEAR(S):

2003 - 1997



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**  
Cabinet Secretary

**Lori Wrotenbery**

Director

**Oil Conservation Division**

April 3, 2003

Mr. Scott T. Pope  
El Paso Field Services  
614 Reilly Ave.  
Farmington, New Mexico 87401

**RE: 2003 SAN JUAN BASIN ANNUAL GROUNDWATER REPORT**

Dear Mr. Pope:

The New Mexico Oil Conservation Division (OCD) has reviewed El Paso Field Services (EPFS) February 28, 2003 "2002 PIT PROJECT ANNUAL GROUNDWATER REPORT". This document contains the results of EPFS's 2002 monitoring and remediation of contaminated ground water related to the closure of unlined oil and gas production pits at 30 sites in the San Juan Basin. The document also requests closure for one site based on the remediation and monitoring actions taken to date.

The OCD's review of the above referenced document is addressed below:

- A. Final pit closure for the site listed below is approved on the condition that the site monitor wells be plugged and abandoned by cutting the casing off below ground surface and filling the casing annulus from bottom to top with a cement grout containing 3-5 % bentonite. Please be aware that OCD approval does not relieve EPFS of responsibility if remaining contaminants pose a future threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve EPFS of responsibility for compliance with any other federal, state, tribal or local laws and regulations.

1. Ramenta et al #1 (Dehy pit) Unit J, Sec. 13, T27N, R09W

Mr. Scott T. Pope  
April 3, 2003  
Page 2

B. A review of the annual ground water reports for the sites listed below shows that the extent of ground water contamination in excess of New Mexico Water Quality Control Commission (WQCC) standards at these sites has not been completely defined. The OCD requires that EPFS install additional ground water monitoring wells at these sites to determine the extent of ground water contamination pursuant to their previously approved ground water investigation plan.

- |     |                        |                             |
|-----|------------------------|-----------------------------|
| 1.  | Fields A#7A            | Unit E, Sec. 34, T32N, R11W |
| 2.  | Hamner #9              | Unit A, Sec. 20, T29N, R09W |
| 3.  | James F Bell #1E       | Unit P, Sec. 10, T30N, R13W |
| 4.  | Johnston Federal #4    | Unit H, Sec. 33, T31N, R09W |
| 5.  | Johnston Federal #6A   | Unit F, Sec. 35, T31N, R09W |
| 6.  | K-27 Line Drip         | Unit E, Sec. 04, T25N, R06W |
| 7.  | K-31 Line Drip         | Unit N, Sec. 16, T25N, R06W |
| 8.  | Lateral 0-21 Line Drip | Unit O, Sec. 12, T30N, R09W |
| 9.  | Standard Oil Com #1    | Unit N, Sec. 36, T29N, R09W |
| 10. | State Gas Com N#1      | Unit H, Sec. 16, T31N, R12W |

If you have any questions, please call me at (505) 476-3491.

Sincerely,



William C. Olson  
Hydrologist  
Environmental Bureau

xc: Denny Foust, OCD Aztec District Office  
Bill Liess, BLM Farmington District Office  
Mike Matush, NM State Land Office  
Bill Freeman, Navajo Nation EPA



STATE OF NEW MEXICO  
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

2040 S. PACHECO  
SANTA FE, NEW MEXICO 87505  
(505) 827-7131

July 8, 1998

**CERTIFIED MAIL**  
**RETURN RECEIPT NO. Z-235-437-304**

Ms. Sandra D. Miller  
El Paso Field Services  
614 Reilly Ave.  
Farmington, New Mexico 87401

**RE: SAN JUAN BASIN ANNUAL GROUNDWATER REPORT**

Dear Ms. Miller:

The New Mexico Oil Conservation Division (OCD) has completed a review of El Paso Field Services (EPFS) February 27, 1998 "RE: 1997 GROUNDWATER ANNUAL REPORT" and accompanying March 1998 "SAN JUAN BASIN PIT CLOSURES, SAN JUAN BASIN, NEW MEXICO, EL FIELD SERVICES PIT PROJECT PIT CLOSURE REPORT" and March 1998 "SAN JUAN BASIN PIT CLOSURE, SAN JUAN BASIN, NEW MEXICO, EL PASO FIELD SERVICES PIT PROJECT GROUNDWATER REPORT ANNUAL REPORT". These documents contain the results of EPFS's 1997 monitoring and remediation of contaminated ground water related to the closure of unlined oil and gas production pits at 57 sites in the San Juan Basin. The documents also requests closure for 11 of the sites based on the remediation and monitoring actions taken to date.

The OCD's review of the above referenced documents is addressed below:

A. The final pit closure, soil remediation and ground water activities conducted at the 10 sites listed below are **approved** and the OCD considers these sites closed.

- |     |                                   |                             |
|-----|-----------------------------------|-----------------------------|
| 1.  | 2C-45 Line Drip (Drip pit)        | Unit P, Sec. 06, T25N, R13W |
| 2.  | Miles Federal #1A (MV) (Drip pit) | Unit F, Sec. 05, T26N, R07W |
| 3.  | Graham #53 (Dehy pit)             | Unit L, Sec. 10, T27N, R08W |
| 4.  | K-17 Line Drip (Drip pit)         | Unit C, Sec. 26, T27N, R08W |
| 5.  | John Charles #8 (Dehy pit)        | Unit B, Sec. 13, T27N, R09W |
| 6.  | Florance C LS #7 (Drip pit)       | Unit F, Sec. 30, T28N, R08W |
| 7.  | Trunk D Line Drip (Drip pit)      | Unit F, Sec. 20, T28N, R08W |
| 8.  | Trujillo GC #1 PC (Drip pit)      | Unit M, Sec. 21, T29N, R10W |
| 9.  | Usselman Gas Com #1 (Drip pit)    | Unit B, Sec. 04, T31N, R10W |
| 10. | Lat H-37 Drip Y-3 (Line drip pit) | Unit F, Sec. 01, T31N, R13W |

Ms. Sandra D. Miller  
July 8, 1998  
Page 2

Please be advised that OCD approval does not relieve EPFS of liability if remaining contaminants are found to pose a future threat to surface water, ground water, human health or the environment. In addition, OCD approval does not relieve EPFS of responsibility for compliance with any other federal, state or local laws and regulations.

B. The closure report for the site listed below shows that ground waters in a piezometer downgradient from the source area at the pit are still contaminated in excess of New Mexico Water Quality Control Commission (WQCC) ground water standards. In addition a review of the data shows that the downgradient extent of contamination has not been completely defined. Therefore, the OCD cannot issue final closure approval at this time and approval of closure actions at this site is **denied**. The OCD requires that EPFS install additional ground water monitoring wells to monitor and determine the extent of ground water contamination pursuant to their previously approved ground water investigation plan.

1. Sheets #2 (Drip pit) Unit H, Sec. 28, T31N, R09W.

C. A review of the annual ground water reports for the sites listed below shows that the extent of ground water contamination in excess of WQCC standards at these sites has not been defined or the sites do not contain permanent downgradient ground water monitoring points. The OCD requires that EPFS install additional ground water monitoring wells at these sites to monitor and determine the extent of ground water contamination pursuant to their previously approved ground water investigation plan.

1. Anderson GC A#1 CH	Unit C, Sec. 28, T29N, R10W
2. D Loop Line Drip	Unit I, Sec. 33, T28N, R08W
3. Hammond #41A	Unit O, Sec. 25, T27N, R08W
4. Horton #1E	Unit H, Sec. 28, T31N, R09W
5. James F Bell #1E	Unit P, Sec. 10, T30N, R13W
6. Jennapah #1	Unit H, Sec. 36, T28N, R09W
7. K-27 Line Drip	Unit E, Sec. 04, T25N, R06W
8. K-31 Line Drip	Unit N, Sec. 16, T25N, R06W
9. Lat 3B-39 Line Drip	Unit M, Sec. 10, T29N, R09W
10. Lat L-40 Line Drip	Unit H, Sec. 13, T28N, R04W
11. Lateral 0-21 Line Drip	Unit O, Sec. 12, T30N, R09W
12. Lindrith B#24	Unit N, Sec. 09, T24N, R03W
13. K-27 Line Drip	Unit E, Sec. 04, T25N, R06W
14. Mesa CPD	Unit C, Sec. 04, T29N, R14W
15. Miles Federal #1A (CH)	Unit F, Sec. 05, T26N, R07W
16. Ramenta Et Al #1	Unit J, Sec. 13, T27N, R09W
17. State Gas Com N#1	Unit H, Sec. 16, T31N, R12W

Ms. Sandra D. Miller

July 8, 1998

Page 3

- D. At the sites listed below EPS proposes to take no further actions until the operator commences remediation associated with their production pits. The OCD is sending letters to the operators of these sites requiring them to investigate and remediate soil and ground water contamination related to their activities. The OCD requests that EPFS work cooperatively with the operator to investigate and remediate contaminated ground water at these sites.

- |     |                                  |                             |
|-----|----------------------------------|-----------------------------|
| 1.  | Canada Mesa #2                   | Unit I, Sec. 24, T24N, R06W |
| 2.  | Coldiron Com A #1                | Unit K, Sec. 02, T30N, R11W |
| 3.  | Fields A #7A                     | Unit E, Sec. 34, T32N, R11W |
| 4.  | Fogelson 4-1 Com #14             | Unit P, Sec. 04, T29N, R11W |
| 5.  | Gallegos Canyon Unit Com A #142E | Unit G, Sec. 25, T29N, R12W |
| 6.  | Johnston Federal #4              | Unit H, Sec. 33, T31N, R09W |
| 7.  | Johnston Federal #6A             | Unit F, Sec. 35, T31N, R09W |
| 8.  | Knight #1                        | Unit A, Sec. 05, T30N, R13W |
| 9.  | Ohio C Govt #3                   | Unit P, Sec. 26, T28N, R11W |
| 10. | Sandoval Gas Com A #1A           | Unit C, Sec. 35, T30N, R09W |
| 11. | Standard Oil Com #1              | Unit N, Sec. 36, T29N, R09W |
| 12. | Turner A #1                      | Unit K, Sec. 34, T31N, R11W |

If you have any questions, please call me at (505) 827-7154.

Sincerely,



William C. Olson  
Hydrologist  
Environmental Bureau

xc: Denny Foust, OCD Aztec District Office  
Bill Liess, BLM Farmington District Office  
Mike Matush, New Mexico State Land Office



STATE OF NEW MEXICO  
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
2040 S. PACHECO  
SANTA FE, NEW MEXICO 87505  
(505) 827-7131

August 6, 1997

**CERTIFIED MAIL**  
**RETURN RECEIPT NO. P-410-431-203**

Mr. Ricky D. Cosby  
El Paso Field Services  
P.O. Box 4990  
Farmington, New Mexico 87499

**RE: SAN JUAN BASIN GROUND WATER REPORTS**

Dear Mr. Cosby:

The New Mexico Oil Conservation Division (OCD) has reviewed El Paso Field Service's (EPFS) June 2, 1997 "SEMI-ANNUAL EL PASO FIELD SERVICES PIT PROJECT GROUND WATER REPORT". This document contains EPFS's a listing of San Juan Basin pit closure sites at which EPFS has encountered ground water and a proposal to modify the reporting schedule for ground water cases from semi-annual to annual.

The above referenced proposal is approved with the following conditions:

1. EPFS will submit the annual reports on investigation/remedial activities to the OCD by December 1 of each respective year. The reports will present the information on each site as a separate case. Each case will contain:
  - a. A description of all investigation remediation activities which occurred during the past year including conclusions and recommendations.
  - b. Summary tables of all past and present laboratory analytic results of ground water quality monitoring including copies of the past years laboratory data sheets and associated quality assurance/quality control data.

Mr. Ricky Cosby  
August 6, 1997  
Page 2

- c. A site map and a quarterly water table elevation map using the water table elevation of the ground water in all monitor wells.
- d. A geologic log and completion diagram for each monitor well.
- e. The disposition of all wastes generated.
- f. Isoconcentration maps for contaminants of concern at the site (ie. benzene, BTEX, chloride, TDS, etc.).

Please be advised that OCD approval does not relieve EPFS of liability if contamination exists which is beyond the scope of the work plan; if the activities fail to adequately determine the extent of contamination; or if the activities fail to adequately remediate or monitor contamination related to EPFS's activities. In addition, OCD approval does not relieve EPFS of responsibility for compliance with any other federal, state or local laws and/or regulations.

If you have any questions, please call me at (505) 827-7154.

Sincerely,



William C. Olson  
Hydrogeologist  
Environmental Bureau

xc: Denny Foust, OCD Aztec District Office  
Bill Liess, BLM Farmington District