

3R - 372

REPORTS

DATE:

JAN 2000

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Well Gas Well X Other Fresh Water Well

2. Name of Operator

Texaco E&P Inc.

3. Address and Telephone No.

3300 N. Butler, Farmington, New Mexico 87401 (505)325-4397

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 2, T26N, R12W, NMPM 1767' FSL & 2094' FWL

5. Lease Designation and Serial No.

SF-078953

6. If Indian, Allottee or Tribe Name

Navajo Tribe

7. If Unit or CA, Agreement Designation

Skelly Oil Company Gallegos Gallup Sand Unit

8. Well Name and No.

Fresh Water Well #80

9. API Well No.

30045-06034

10. Field and Pool, or Exploratory Area

Ojo Alamo

11. County or Parish, State

San Juan County, NM


12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- X Notice of Intent
Subsequent Report
Final Abandonment Notice

TYPE OF ACTION

- X Abandonment
Recompletion
Plugging Back
Casing Repair
Altering Casing
Other
Change of Plans
New Construction
Non-Routine Fracturing
Water Shut-Off
Conversion to Injection
Dispose Water



(Note: Report results of multiple completion on well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco requests approval to plug and abandon the captioned fresh water well. Due to a lack of downhole information, the proposed P&A is based on our best judgement. Please see the attached P&A procedure.

On 11/30/99, Texaco received a letter from the Bureau of Indian Affairs, Ms. Linda Taylor, requesting us to plug and abandon this fresh water well. According to their records, the well was once used by the Skelly Oil Company and since Getty acquired Skelly and likewise Texaco acquired Getty, it remains our responsibility to close the subject well.

We respectfully request your immediate attention on this matter.

If you require any additional information, please contact Larry Schlotterback @ (505) 325 4397 x17.

14. I hereby certify that the foregoing is true and correct

Signed

[Signature]

Title Senior Engineer

Date 1/19/00

(This space for Federal or State office use)

Approved by

[Signature]

Title

Date

JAN 20 2000

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department of agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Plug and Abandonment Procedure For:

**Skelly Oil Company
Gallegos Gallup Sand Unit
Fresh Water Well #80
Section 2, T26N, R12W, NMPM
1767' FSL / 2094' FWL**

Texaco Exploration and Production, Inc., 3300 North Butler, Farmington, New Mexico 87401, will conduct the plugging procedure.

1. Rig up swabbing unit on location
2. Run 1" working string to TD (estimated depth 300') *Recorded TD of 242'
4 1/2" casing*
3. Pump Class C cement from bottom to surface
4. As requested by the Bureau of Indian Affairs, casing will be cut off 3-4 feet from surface for plow clearance.