

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Targa Midstream Services L.P.	Contact: James Lingnau
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (505) 394-2534
Facility Name: Eunice North Compressor Station	Facility Type: Natural Gas Compressor Station
Surface Owner: Versado Gas Processors, L.P.	Mineral Owner: API No.

LOCATION OF RELEASE

Unit Letter	Section 28	Township 21S	Range 37 E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	---------------	-----------------	---------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.4508 N Longitude -103.1622 W

NATURE OF RELEASE

Type of Release: Natural Gas leak on compressor ignited.	Volume of Release: Approximately 250 Mcf of Natural Gas leaked but was burned.	Volume Recovered None
Source of Release: Natural Gas Compressor	Date and Hour of Occurrence 10/09/07 12:15 PM MT	Date and Hour of Discovery Same
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink Hobbs OCD	
By Whom? Cal Wrangham	Date and Hour 10/09/07 12:30 PM MT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Natural Gas leak on Natural Gas compressor that found ignition source and started a fire.		
Describe Area Affected and Cleanup Action Taken.* North Compressor Station Engine Room. The incident was investigated, and no liquid loss was reported. Repairs were made and operation restored.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Cindy Klein</i>	OIL CONSERVATION DIVISION	
Printed Name: Cindy Klein	Approved by Environmental Specialist: <i>Bradford Billings</i>	
Title: ES&H Supervisor	Approval Date: 09/23/2020	Expiration Date:
E-mail Address: CynthiaKlein@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9-23-2020 Phone: (575) 396-4220 ext. 238		

* Attach Additional Sheets If Necessary

nBGB2026844255