

andrew@rthicksconsult.com

From: andrew@rthicksconsult.com
Sent: Friday, October 18, 2019 5:36 PM
To: 'EMNRD-OCD-District1spills@state.nm.us'
Cc: 'dharwell@advanceenergypartners.com'
Subject: Wool Head 20 State Com 003 Battery Release Notification

NMOCD:

On the behalf of Advance Energy Partners Hat Mesa LLC, R.T. Hicks Consultants submits this email as the 24-hour notification of a major release (>25 bbls). A C-141 will be submitted within 15-days of this notification.

Date of discovery: October 18, 2019 at 09:00 hrs.
Responsible Party: Advance Energy Partners Hat Mesa LLC
Location Name: Wool Head 20 State Com #003 Tank Battery
API: 30-025-42142
Coordinates: 32.458389, -103.600912 (NAD83)
UL, Sec. T.R.: M-30-21S-R33E

The knockout valve at the tank battery failed. Approximately 350 bbls (320 bbls produced water; 30 bbls of oil) was contained within the battery's secondary containment and recovered. A calculated 36 bbls of produced water and oil was release onto the production pad and windblown onto pasture land.

Andrew Parker
R.T. Hicks Consultants
Durango Field Office
Cell: (970) 570-9535

NRM2000358734