District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NCE2002452675
District RP	
Facility ID	
Application ID	

A3V68-191125-C-1410

Release Notification

Responsible Party

Responsible Party	OGRID
Contact Name Charles R. Beauvais II	Contact Telephone 575-988-2043
Contact email charles.r.beauvais@conocophillips.com	Incident # *(assigned by OCD)*
Contact mailing address 15 W London Rd, Loving, NM 88256	

Location of Release Source

Latitude 32°0'49" N 32.01361 Longitude 103°40'18" W -103.6717

(NAD 83 in decimal degrees to 5 decimal places)

Site Name Battle Axe	Site Type Water Transfer Line - On Pad - Over Secondary Containment
Date Release Discovered 11/25/2019	API# *(if applicable)*

Unit Letter	Section	Township	Range	County
	28	26S	32E	Lea County

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (*Name:* BLM)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☒ Crude Oil	Volume Released (bbls) 2.4 bbls	Volume Recovered (bbls) 2.4 bbls
☒ Produced Water	Volume Released (bbls) 45.9 bbls	Volume Recovered (bbls) 45.9 bbls
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☒ Yes ☐ No
☐ Condensate	Volume Released (bbls) 0, NA	Volume Recovered (bbls) 0, N/A
☐ Natural Gas	Volume Released (Mcf) 0, NA	Volume Recovered (Mcf) 0, N/A
☐ Other (describe)	Volume/Weight Released (provide units) 0, N/A	Volume/Weight Recovered (provide units) 0, N/A

Cause of Release

Ball valve developed a pin hole leak. Ball valve is being replaced and Lone Star was called out the vac out 100% of the release from secondary containment and place back in appropriate tank.

Repair made on 11/25/19, replaced ball valve

Remediation completed on 11/25/19, Secondary containment cleaned out w/ vac truck.

Form C-141
Page 2

State of New Mexico
Oil Conservation Division

Incident ID	NCE2002452675
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☒ Yes ☐ No	If YES, for what reason(s) does the responsible party consider this a major release? 19.15.29.7(A)(1) An unauthorized release of a volume, excluding gases, of 25 barrels or more.

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
Notice was made by Charles Beauvais, Environmental Coordinator, at P.M. on 11/25/19 via email to bradford.billings@state.nm, Also, an online submittal with payment for submittal was made to NMOCD

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Charles R. Beauvais II Title: Environmental Coordinator
Signature: Charles R. Beauvais II Date: 11/25/2019
email: charles.r.beauvais@conocophillips.com Telephone: 1-575-988-2043

OCD Only

Received by: **Rejected** Date: **01/24/2020**