

NCE2002756541

<b>Location:</b>	<b>PLU 261</b>	
<b>Spill Date:</b>	<b>11/18/2019</b>	
<b>Area 1</b>		
Approximate Area =	245.00	sq. ft.
Average Saturation (or depth) of spill =	2.00	inches
Average Porosity Factor =	0.15	

<b>VOLUME OF LEAK</b>		
Total Produced Water =	1.09	bbls
<b>Area 2</b>		
Approximate Area =	1260.00	sq. ft.
Average Saturation (or depth) of spill =	0.25	inches
Average Porosity Factor =	0.03	

<b>VOLUME OF LEAK</b>		
Total Produced Water =	0.14	bbls
<b>TOTAL VOLUME OF LEAK</b>		
Total Produced Water =	141.23	bbls
<b>TOTAL VOLUME RECOVERED</b>		
Total Produced Water =	140.00	bbls