

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NCE2003542701
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party ConocoPhillips Company	OGRID 217817
Contact Name Gustavo Fejervary	Contact Telephone 432/210-7037
Contact email g.fejervary@cop.com	Incident # (assigned by OCD)
Contact mailing address 5735 SW 7000 Andrews, TX 79714	

### Location of Release Source

Latitude 32.788462 Longitude -103.475532  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name EVGSAU 3332-519	Site Type flow line leak
Date Release Discovered 01/10/2020	API# (if applicable)

Unit Letter	Section	Township	Range	County
I	32	17S	35E	Lea

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 10	Volume Recovered (bbls) 2.5
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 55.5	Volume Recovered (bbls) 2.5
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release Flowline rupture


State of New Mexico  
Oil Conservation Division

Incident ID	NCE2003542701
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?  it exceeded the 25bbbls defined by the Major release definition
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?  It was given on 1/10/20 to district 1 email address and Bradford Billings	

**Initial Response**

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:  	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Gustavo Fejervary</u>	Title: <u>Environmental Coordinator</u>
Signature: 	Date: <u>1/21/20</u>
email: <u>g.fejervary@cop.com</u>	Telephone: <u>432/210-7037</u>
<b><u>OCD Only</u></b>	
Received by: _____	Date: _____

NCE2003542701

L48 Spill Volume Estimate Form												
Facility Name & Number:		EVGSAU 3332-519										
Asset Area:		SENI (BUCKEYE)										
Release Discovery Date & Time:		1/9/2020 10:30AM										
Release Type:		Oil Mixture										
Provide any known details about the event: Flowline leak												
Spill Calculation - On Pad Surface Pool Spill												
Convert Irregular shape into a series of rectangles	Length (ft.)	Width (ft.)	Deepest point in each of the areas (in.)	No. of boundaries of "shore" in each area	Estimated Pool Area (sq. ft.)	Estimated Average Depth (ft.)	Estimated volume of each pool area (bbl.)	Penetration allowance (ft.)	Total Estimated Volume of Spill (bbl.)	Percentage of Oil if Spilled Fluid is a Mixture	Total Estimated Volume of Spilled Oil (bbl.)	Total Estimated Volume of Spilled Liquid other than Oil (bbl.)
Rectangle A	90.0	60.0	0.50	4	5400.000	0.010	10.013	0.001	10.018	15.14%	1.517	8.501
Rectangle B	40.0	10.0	0.50	3	400.000	0.014	0.989	0.001	0.990	15.14%	0.150	0.840
Rectangle C	30.0	7.0	0.50	3	210.000	0.014	0.519	0.001	0.520	15.14%	0.079	0.441
Rectangle D					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!		#DIV/0!	#DIV/0!
Rectangle E					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!		#DIV/0!	#DIV/0!
Rectangle F					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!		#DIV/0!	#DIV/0!
Rectangle G					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!		#DIV/0!	#DIV/0!
Rectangle H					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!		#DIV/0!	#DIV/0!
Rectangle I					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!		#DIV/0!	#DIV/0!
Rectangle J					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!		#DIV/0!	#DIV/0!
Total Volume Release:									11.527		1.745	9.782

NCE2003542701

L48 Spill Volume Estimate Form									
Facility Name & Number:		EVGSAU 3332-519							
Asset Area:		SENM (BUCKEYE)							
Release Discovery Date & Time:		1/9/2020 10:30AM CST							
Release Type:		Oil Mixture							
Provide any known details about the event: Flowline Leak: Five barrels were recovered									
Spill Calculation - Subsurface Spill - Rectangle									
<div> <div>Was the release on pad or off-pad?</div> <div>Yes, On Pad - 8%; Off Pad - 13.57% soil spilled-fluid saturation factor, if No, use factors above.</div> </div>									
Convert Irregular shape into a series of rectangles	Length (ft.)	Width (ft.)	Depth (in.)	Soil Spilled-Fluid Saturation	Estimated volume of each area (bbl.)	Total Estimated Volume of Spill (bbl.)	Percentage of Oil if Spilled Fluid is a Mixture	Total Estimated Volume of Spilled Oil (bbl.)	Total Estimated Volume of Spilled Liquid other than Oil (bbl.)
Rectangle A	60.0	90.0	4.00	15.12%	320.400	48.444	15.14%	7.334	41.110
Rectangle B	40.0	10.0	4.00	15.12%	23.733	3.588	15.14%	0.543	3.045
Rectangle C	30.0	7.0	4.00	15.12%	12.460	1.884	15.14%	0.285	1.599
Rectangle D					0.000	0.000		0.000	0.000
Rectangle E					0.000	0.000		0.000	0.000
Rectangle F					0.000	0.000		0.000	0.000
Rectangle G					0.000	0.000		0.000	0.000
Rectangle H					0.000	0.000		0.000	0.000
Rectangle I					0.000	0.000		0.000	0.000
Rectangle J					0.000	0.000		0.000	0.000
Total Volume Release:						53.917		8.163	45.754