

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2004934825
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	Enterprise Field Services LLC	OGRID	241602
Contact Name	Alena Miro	Contact Telephone	575-628-6802
Contact email	ammiro@eprod.com	Incident # (assigned by OCD)	
Contact mailing address	PO Box 4324, Houston, TX 77210		

Location of Release Source

Latitude See Attached Email Longitude See Attached Email
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	1009 Pipeline	Site Type	Pipeline ROW
Date Release Discovered	2/3/2020	API# (if applicable)	N/A

Unit Letter	Section	Township	Range	County
See Attached Email				

Surface Owner: State Federal Tribal See Attached Email

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Natural Gas	Volume Released (Mcf) See Attached Email	Volume Recovered (Mcf) 0 MCF
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release:

Natural gas was released due to a controlled pipeline blow down to evacuate the pipeline.

Form C-141


State of New Mexico
Oil Conservation Division

Incident ID	NRM2004934825
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? The release is considered a major release as the estimated volume of gas released exceeded the major release thresholds as defined in 19.15.29.7(A) NMAC.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Yes; Jim Griswold, OCD Region 1 and OCD Region 2 were notified via email of all information contained in the initial notification C-141 form on 2/4/20 at 3:23 pm.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: N/A - Gas only release.	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Jon E. Fields</u> Signature:  email: <u>jefields@eprod.com</u>	Title: <u>Director, Field Environmental</u> Date: <u>2/13/2020</u> Telephone: <u>713-381-6684</u>
OCD Only Received by: <u>Ramona Marcus</u> Date: <u>02/18/2020</u>	

Form C-141

State of New Mexico
Oil Conservation Division

Page 6

Incident ID	NRM2004934825
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

A scaled site and sampling diagram as described in 19.15.29.11 NMAC


Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)

Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)

Description of remediation activities

N/A - Gas only release

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Jon E. Fields Title: Director, Field Environmental
 Signature:  Date: 2/13/2020
 email: jefields@eprod.com Telephone: 713-381-6684

OCD Only

Received by: Ramona Marcus Date: 02/18/2020

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: _____ Date: _____

Printed Name: _____ Title: _____

NRM2004934825

Miro, Alena

From: Miro, Alena
Sent: Tuesday, February 4, 2020 3:23 PM
To: 'EMNRD-OCD-District1spills@state.nm.us'; 'blm_nm_cfo_spill@blm.gov'; 'Bratcher, Mike, EMNRD'
Cc: Reinermann, Paul; Mendez, Brenda
Subject: 2020-02-3/4 Release Notification

Importance: High

Good afternoon,

Please be advised that a controlled pipeline blowdowns occurred on February 3rd at approximately 1530 MST (#1 and #2 below) and February 4th at approximately 1230 MST (#3 below) on Enterprise Line Pipeline ROW #1009 at the below GPS locations.

Please find the below additional information as required by NMAC 19.15.29.10.A(1):

OGRID: 241602
 Contact Name: Alena Miro
 Contact Telephone: 575-628-6802
 Contact Email: ammiro@eprod.com
 Contact Mailing Address: PO Box 4324, Houston, TX 77210

1. N32.427293/W-103.640383
 - 1.67 MMscf of gas
 - Unit Letter: A
 - Section: 2
 - Township: 22S
 - Range: 32E
 - County: Lea
 - Surface Owner: Federal (BLM)

2. N32.44631/W-103.566090
 - 1.67 MMscf of gas
 - Unit Letter: L
 - Section: 27
 - Township: 21S
 - Range: 33E
 - County: Lea
 - Surface Owner: Merchant Livestock Company

3. N32.361530/W-103.89355
 - 1.17 MMscf of gas
 - Unit Letter: L
 - Section: 28
 - Township: 22S
 - Range: 30E
 - County: Eddy
 - Surface Owner: Federal (BLM)

NRM2004934825

This email contains the remainder of the information needed to meet immediate notification requirements of NMAC Section 19.

The source of the release has been stopped, impacted areas have been secured to protect human health and the environment, no liquid materials were released and no free liquids and recoverable material was required to be removed and managed.

A formal C-141 form will be forward to your office via the NMOCD online submittal portal shortly.

Please let me know if you have any questions pertaining to this event.

Thank you,

Alena Miro
Senior Environmental Engineer
Enterprise Products
575-628-6802

NRM2004934825

Facility : line 1009 west end 7.52 miles

Date : 2/4/2020

Enter data in shaded fields to calculate gas volumes released due to leak and/or blowdown of system.

Hours of leak		
Diameter of hole (inches)		
Line Pressure at Leak		
Volume of Gas Leaked	0.00	

Hourly Basis 0.00 MSCF

Rectangle or Line Crack

Length, in.	
Width, in.	
Eqv. Diameter, in.	#DIV/0!

NOTE: Enter Components on the Gas Leak or Gas Blowdown sheet as needed.

Calculations:
 Volume of Gas Leaked (MSCF) = Diameter*(Upstream Gauge Pressure + Atmospheric Pressure)*Hours of Leak
 **Reference: Pipeline Rules of Thumb Handbook, 3rd Edition, McAllister. Page 260. Assuming Standard Temperature and Pressure (14.7 psi and 60 F)

Footage of Pipe blowdown	39705
Initial line pressure	460
Diameter of Pipe (inches)	12
Volume of Gas Blown Down	1166.77596

MSCF

Calculations:
 Volume of Gas Blown Down (MSCF) = Volume at pipeline conditions (ft³)*(Gauge Pressure (psig)+Atmospheric Pressure (13.7 psi)*Standard Temperature (60F)
 /(1000 scf/mscf)*Standard Pressure (14.7psig)*Temperature(F)*Z Factor
 Volume at pipeline conditions (scf) = Diameter/12 (ft)*Diameter/12 (ft)*Pi/4* Length of pipe (ft)
 **Reference: Gas Pipeline Hydraulics, Menson (2005) Pages 132-134. Assuming the Ideal Gas Law and Tpipeline = Tatm.

Total Gas Loss	1166.78	MSCF	1.167	MMSCF
-----------------------	----------------	-------------	--------------	--------------

Cause/ Reason: Blow down for safety reasons after the line rupture. GPS of the blow down N 32.361530/W 103.89355
Corrective Action: Blown down for safety BLM

S28 T22S R30E NWSW
 Name: Steve Kutchach III

Cell Phone: 303 301 4375

NRM2004934825

Facility : line 1009 East end 16.6 miles **Date :** 2/3/2020

Enter data in shaded fields to calculate gas volumes released due to leak and/or blowdown of system.

Hours of leak	
Diameter of hole (inches)	
Line Pressure at Leak	
Volume of Gas Leaked	0.00

Hourly Basis 0.00 MSCF

Rectangle or Line Crack

Length, in.	
Width, in.	
Eqv. Diameter, in.	#DIV/0!

NOTE: Enter Components on the Gas Leak or Gas Blowdown sheet as needed.

Calculations:
 Volume of Gas Leaked (MSCF) = Diameter*(Upstream Gauge Pressure + Atmospheric Pressure)*Hours of Leak
 **Reference: Pipeline Rules of Thumb Handbook, 3rd Edition, McAllister, Page 260. Assuming Standard Temperature and Pressure (14.7 psi and 60 F)

Footage of Pipe blowdown	87648
Initial line pressure	600
Diameter of Pipe (inches)	12
Volume of Gas Blown Down	3335.24902

MSCF

Calculations:
 Volume of Gas Blown Down (MSCF) = Volume at pipeline conditions (ft³)*(Gauge Pressure (psig)+Atmospheric Pressure 13.7 psi)*Standard Temperature (60F)
 /((1000 scf/mscf)*Standard Pressure (14.7psi)*Temperature(ft)*Z Factor
 Volume at pipeline conditions (scf) = Diameter/12 (ft)*Diameter/12 (ft)*Pi/4* Length of pipe (ft)
 **Reference: Gas Pipeline Hydraulics, Menson (2005) Pages 132-134. Assuming the Ideal Gas Law and Tpipeline = Tatm.

Total Gas Loss	1667.62 MSCF	1.668 MMSCF
-----------------------	---------------------	--------------------

Cause/ Reason: Blow down for safety reasons after the line rupture. GPS of blow downs N32.44631/W103.566090 and N32.427293/W103.640383
Corrective Action: Blown down for safety

Name: Steve Kutach III **Cell Phone:** 303 301 4375