

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2009840225
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party BXP Operating, LLC	OGRID 329487
Contact Name M.Y. Merchant	Contact Telephone 575-492-1236
Contact email mymerch@penrocoil.com	Incident # (assigned by OCD)
Contact mailing address P.O. Box 2769 Hobbs, NM 88240	

Location of Release Source

Latitude 32.1719856 _____ Longitude -103.1870193 _____
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Langlie Jal Unit #20	Site Type Injection Well
Date Release Discovered 4/2/2020	API# (if applicable) 30-025-11313

Unit Letter	Section	Township	Range	County
K	32	24S	37E	LEA

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 10	Volume Recovered (bbls) 6
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)


Cause of Release: Injection trunk line had a rotten pipe, dug up, and replaced jt.

Incident ID	NRM2009840225
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Over 5 bbl leak
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Brandon with NM Land Office discovered the leak and reported to us 4/2/2020.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why: _____ _____ _____
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>M.Y. Merchant</u> Title: <u>Production Supervisor</u> Signature:  Date: <u>4/3/2020</u> email: <u>mymerch@penrocoil.com</u> Telephone: <u>575-492-1236</u>
<u>OCD Only</u> Received by: <u>Ramona Marcus</u> Date: <u>4/7/2020</u>