

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Incident ID	NRM2013358062
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	ConocoPhillips	OGRID	217817
Contact Name	Kelsy Waggaman	Contact Telephone	(505) 577-9071
Contact email	Kelsy.Waggaman@ConocoPhillips.com	Incident #	(assigned by OCD)
Contact mailing address	29 Vacuum Complex Lane, Lovington, NM 8826		

Location of Release Source

Latitude 32.8224 Longitude -103.7903
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Elvis #1	Site Type	Battery
Date Release Discovered	4/30/20	API#	(if applicable)

Unit Letter	Section	Township	Range	County
F	20	T17S	R32E	Lea County, NM

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 8.17	Volume Recovered (bbls) 7
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Check valve corrosion

Incident ID	NRM2013358062
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why:
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>Kelsy Waggaman</u> Title: <u>Environmental Coordinator</u> Signature: <u></u> Date: <u>5/5/20</u> email: <u>Kelsy.Waggaman@gmail.com</u> Telephone: <u>(505) 577-9071</u>
<u>OCD Only</u> Received by: <u>Ramona Marcus</u> Date: <u>5/12/2020</u>

NRM2013358062

L48 Spill Volume Estimate Form									
Facility Name & Number:		Elvis Battery							
Asset Area:		MALJAMAR							
Release Discovery Date & Time:		10:30AM 4/30/2020							
Release Type:		Produced Water							
Provide any known details about the event:		Failed check valve caused a produced water spill/ 7 bbls recovered with vac truck. Volume below is left in soil							
Spill Calculation - Subsurface Spill - Rectangle									
Was the release on pad or off-pad?		On Pad - 10.5%; Off Pad - 15.12% soil spilled-fluid saturation factor							
Has it rained at least a half inch in the last 24 hours?		Yes, On Pad - 8%; Off Pad - 13.57% soil spilled-fluid saturation factor; if No, use factors above.							
Convert Irregular shape into a series of rectangles	Length (ft.)	Width (ft.)	Depth (in.)	Soil Spilled-Fluid Saturation	Estimated volume of each area (bbl.)	Total Estimated Volume of Spill (bbl.)	Percentage of Oil if Spilled Fluid is a Mixture	Total Estimated Volume of Spilled Oil (bbl.)	Total Estimated Volume of Spilled Liquid other than Oil (bbl.)
Rectangle A	30.0	18.0	0.10	10.50%	0.801	0.084			
Rectangle B	40.0	35.0	0.50	10.50%	10.383	1.090			
Rectangle C					0.000	0.000			
Rectangle D					0.000	0.000			
Rectangle E					0.000	0.000			
Rectangle F					0.000	0.000			
Rectangle G					0.000	0.000			
Rectangle H					0.000	0.000			
Rectangle I					0.000	0.000			
Rectangle J					0.000	0.000			
Total Volume Release:						1.174			