

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian LTD	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	McKittrick 11-5 SWD Facility	Facility Type	SWD Facility
Surface Owner	Mineral Owner	Lease No. NM 53219, API#30-015-33168	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	11	22	24					Eddy County, NM

Latitude N 32.41420 Longitude W 104.47431

NATURE OF RELEASE

Type of Release	Produced water & oil	Volume of Release	200 bbls water & trace amts oil	Volume Recovered	0 bbls
Source of Release	Disposal pump failure	Date and Hour of Occurrence	03/20/2012 @ 5:00 a.m.	Date and Hour of Discovery	03/20/2012 @ 10:44 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD Terry Gregston- BLM		
By Whom?	Leslie Moreno	Date and Hour	03/20/2012 @ 3:30 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse,			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Disposal pump failure caused 200 bbls of water and trace amounts of oil to leak onto the ground. Pump was repaired and 0 bbls were recovered. Remediation efforts continue and will be performed according to NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken.*

The area affected was approximately 30' x 30'. Remediation was completed in accordance with the remediation plan approved by NMOCD on 11/13/2012 via email from Mike Bratcher and approved by the BLM on 12/10/2012 via email from Terry Gregston.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Chris Jones		Approved by District Supervisor: Bradford Billings (Santa Fe)	
Title: HES Specialist		Approval Date: 10/28/2019	Expiration Date:
E-mail Address: chris.jones@oxy.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/4/13	Phone (575) 397-8216		

* Attach Additional Sheets If Necessary