

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Co., LP 6137	Contact: Jennifer Van Curen
Address: PO Box 250; Artesia, NM 88211	Telephone No. 505-748-0160
Facility Name Warthog 2 State Well #002	Facility Type Battery

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter H	Section 2	Township 23S	Range 28E	Feet from the 1980	North/South Line North	Feet from the 660	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Water	Volume of Release: unknown	Volume Recovered: 0 bbls
Source of Release: Water Hauler	Date and Hour of Occurrence: AM sometime	Date and Hour of Discovery: 3-27-06 @ 7:00 am
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? Mike Bratcher--OCD	3/13/06
By Whom? David Purdy; Lease Operator	Date and Hour: 3-27-06 3/13/06 11:04 AM	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

When Lease Operator went to check on battery, he found that there was a spill on the South side of the battery. After inspection, lease operator discovered that a water hauler had dumped fluids to the south of the location in the pasture.

Describe Area Affected and Cleanup Action Taken.*

The area affected was 70' X 200'. Water Dump was called into the OCD by Roy White and BJ Cathey. BJ talked to Mike Bratcher. Will visit with OCD to see what clean up action needs to take place.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature <i>Jennifer Van Curen</i>		OIL CONSERVATION DIVISION	
Printed Name: Jennifer Van Curen		Approved by District Supervisor: TIM GUM by MB <i>Mike Bratcher</i>	
Title: Production Field Tech		Approval Date: 4/9/07	Expiration Date:
E-mail Address: Jennifer.Vancuren@dvnm.com		Conditions of Approval:	
Date: 3/27/06 Phone: 748-0160		Attached ☒	

* Attach Additional Sheets If Necessary



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Devon Energy Production Co., LP
P.O. Box 250
Artesia, NM 88211
ATTN: Environmental Department

April 9, 2007

Reference: **Warthog 2 State #2 02-23S-28E API # 30-015-27180 Eddy County, New Mexico**

Operator,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of an Initial Report Form C-141 reporting a release of produced fluids that occurred on or about March 13, 2006 at the above referenced well site. Please submit a work plan proposal (plan) for remediation, removal and/or clean up of contaminants that may be present at this site. The plan is to be formulated based on vertical and horizontal delineation of contamination, site ranking, and OCD Rules and Guidelines.

A publication outlining OCD guidelines and requirements for site ranking and spill remediation can be found on the OCD website as follows: <http://www.emnrd.state.nm.us/ocd> Click on each of the following items as they appear:

- Publications
- Environmental Handbook
- Miscellaneous Guidelines
- Remediation of Leaks, Spills and Releases

Please submit this plan to the OCD District 2 office no later than May 9, 2007. Please include any remedial or clean up actions that have already been performed.

Remediation requirements may be subject to other federal, state, local laws and/or regulations.

If I can be of assistance in this matter, my contact information is listed below.

Sincerely,

Mike Bratcher
NMOCD District 2
1301 W. Grand Ave.
Artesia, NM 88210
(505) 748-1283 Ext. 108
(505) 626-0857
mike.bratcher@state.nm.us

Tracking number: nLLB0631147792