

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87418  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**RECEIVED**  
OCT 09 2019  
**HOBBSOCD**

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186
Facility Name Turner Battery (nearest well Turner #22)	Facility Type Battery
Surface Owner Deck Estate	Mineral Owner State
Lease No. 30-025-37203	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	22	21S	37E	1980	FSL	1980	FWL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Produced Water and Oil	Volume of Release 130wtr/50oil	Volume Recovered 125wtr/45oil
Source of Release Water leg on gun bbl	Date and Hour of Occurrence 10/1/09 1:00pm	Date and Hour of Discovery 10/1/09 1:45pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Leiking	
By Whom? Natalie Gladden	Date and Hour 2pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Water leg on the gun bbl, plugged up causing the tanks to overflow. All fluid remained inside the containment walls.		
Describe Area Affected and Cleanup Action Taken.* Vacuum trucks were called out to recover standing fluid. Hyrdotech will be out 10/2 to vacuum out contaminated soil. Contaminated soil will be hauled off to Sundance Disposal.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

GW 10/1/09

Signature: <i>Natalie Gladden</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Natalie Gladden	Approved by: <i>Jeff Leiking</i> ENV ENGINEER: District Supervisor	
Title: EH&S Environmental Tech	Approval Date: 10/09/09	Expiration Date: 12/09/09
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SUBMIT FINAL C-141 BY 12/09/09.	Attached <input type="checkbox"/> IRP-09.10.2304
Date: 10/1/09 Phone: 575/390-4186		

\* Attach Additional Sheets If Necessary

FGRL0928757083