

<b>Location:</b>	BEU 039 (30-015-20945)	
<b>Spill Date:</b>	2/21/2019	
<b>Length of Spill=</b>	17.00	feet
<b>Width of Spill=</b>	12.00	feet
<b>Saturation (or depth) of Spill=</b>	8.00	inches
<b>Approximate Oil %</b>	100	
<b>Porosity Factor=</b>	0.03	
<b>Volume Recovered=</b>	5.00	bbls

VOLUME OF LEAK		
<b>Total Oil=</b>	5.7	barrels
<b>Total Produced Water=</b>	-	barrels

VOLUME RECOVERED		
<b>Total Oil=</b>	5.0	barrels
<b>Total Produced Water=</b>	-	barrels