

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company OXY USA Inc.	Contact Eric Maestas
Address 770 Rosebud Rd. Amistad NM 88410	Telephone No. 575-420-7825
Facility Name Bravo Dome Gathering System	Facility Type Carbon Dioxide Gathering System
Surface Owner Culbertson	Mineral Owner Culbertson
API No. 30-021-20111	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	12	18 N	30 E	1980	North	1980	East	Harding

Latitude N 35.80640 Longitude W -103.70278

**NATURE OF RELEASE**

Type of Release Carbon Dioxide Gas	Volume of Release 1000 MCF	Volume Recovered None
Source of Release- Pipeline Vent	Date and Hour of Occurrence 3/09/2017 8:00 AM	Date and Hour of Discovery 3/09/2017 8:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Bayliss	
By Whom? Eric Maestas	Date and Hour 3/9/2017 1:31 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*


CO2 gas was vented to repair a leak on a flanged fitting on the SW field Scrubber of Bravo Dome CO2 Gas Unit SW Collection System. Wells were shut in, trunk line and lateral block valves were closed to minimize vent, and lines were bled down to atmosphere. There was no produced water lost.

Describe Area Affected and Cleanup Action Taken.\*

N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 	Approved by Environmental Specialist:	
Printed Name: Eric Maestas	Approval Date:	Expiration Date:
Title: HES Coordinator	Conditions of Approval:	
E-mail Address: eric_maestas@oxy.com	Attached <input type="checkbox"/>	
Date: <u>3/13/2017</u> Phone: 575-420-7825		

\* Attach Additional Sheets If Necessary