

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit 190H; 2RP #2524	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-42145	


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	36	22S	30E	630	North	370	East	Eddy

Latitude: N 32.354081° Longitude: W 103.826720°

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 5 bbls crude oil and 33 bbls produced water	Volume Recovered: 2 bbls crude oil and 1 bbl produced water
Source of Release: 2" hammer union	Date and Hour of Occurrence: 9/28/14 @ unknown	Date and Hour of Discovery: 9/28/14 @ approx. 2:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher and H. Patterson	
By Whom? Tony Savoie	Date and Hour: 9/28/14 @ 6:53 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* There was a pulling unit on-site, a hammer union was left loose. The hammer union was re-tightened.		
Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 11,000 sq. ft. of caliche well pad with mostly produced water and misted approximately 15,000 sq. ft. of pasture area with crude oil. The pasture area was treated with micro-blaze. Soil samples were collected, analyzed and based on laboratory analytical results the release area has been excavated and contaminated soil hauled to a state approved disposal facility. A liner was installed over the areas of SP6 and SP7 then the excavation was backfilled with clean soil. The area has been remediated in accordance with the NMOCD and BLM remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Bradley Blevins		Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 3/4/2015	Expiration Date: N/A	
E-mail Address: bblevins@basspet.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: <u>2-11-15</u>	Phone: 432-214-3704		

* Attach Additional Sheets If Necessary

2RP-2524