

Received 3/3/2015

NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 450Y; 2RP #2758	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-42651	

LOCATION OF RELEASE

Unit Letter B	Section 27	Township 24S	Range 30E	Feet from the 116	North/South Line North	Feet from the 1524	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.19633° Longitude: W 103.56520°

NATURE OF RELEASE

Type of Release: crude oil	Volume of Release: 7 bbls	Volume Recovered: none
Source of Release: flow line connection	Date and Hour of Occurrence: 1/15/15 @ unknown	Date and Hour of Discovery: 1/15/15 @ approx. 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* A hammer union on the flow line became loose. The union was re-tightened.		
Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 1,100 sq. ft. of pasture and pad area with a light mist of less than 1/2" saturation. It also puddled up in the pasture in an area measuring approximately 726 sq. ft. The BLM was notified the day of the release; an EPI remediation crew began removing the saturated soil on 1/16/15 and continued on 1/19/15, a total of 84 cubic yards of soil and caliche was hauled to Lea Land and clean soil was stockpiled on-site pending the out-come of the soil samples collected on 1/16/15. Based on laboratory analytical results the release area has been excavated and contaminated soil hauled to a state approved disposal facility. The excavation has been backfilled with clean soil. The area has been remediated in accordance with the NMOCD and BLM remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 3/5/2015	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 2-11-15	Phone: 432-214-3704	

* Attach Additional Sheets If Necessary

2RP-2758