

March 13, 2015

Oil Conservation Division District 2 – Artesia 811 S. First St. Artesia, NM 88210

Re: Canvasback 13 Federal #2H

30-015-40538 Sec. 13, T24S-R31E Eddy County, NM

Mr. Mike Bratcher,

COG Operating LLC would like to submit the enclosed document for closure of the above captioned well. The plan is in response to the C-141 Initial report dated August 17, 2014.

All work has been completed in accordance with the approved work plan submitted to the NMOCD and BLM.

A signed C-141 Final is enclosed for your consideration. Please feel free to contact me with any questions or concerns at (575) 748-6933.

Sincerely,

Lupe Carrasco

**Environmental Coordinator** 

Enclosure(s): C-141 Final

District I
1625 N. French Dr., Hobbs, NM 88240
District III
1301 W. Grand Avenue, Artesia, NM 88210
District IIII
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised October 10, 2003

Jamit 2 Copies to appropriate

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Attached

## **Release Notification and Corrective Action OPERATOR** Initial Report Name of Company COG OPERATING LLC Contact Robert McNeill 600 West Illinois Avenue, Midland, TX 79701 Address Telephone No. 432-230-0077 Facility Name: Canvasback 13 Federal #2H Facility Type: Flowline Surface Owner: Federal Mineral Owner: Federal Lease No. (API#) 30-015-40538 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County Α 13 **24S** 31E 330 North 480 East Eddy Latitude N32' 13.476 Longitude W103' 43.375 NATURE OF RELEASE Type of Release Volume of Release Volume Recovered Produced Water 70 bbls 25 bbls Source of Release Date and Hour of Occurrence Date and Hour of Discovery 4" poly waterline 8/03/2014 2:30 pm 8/03/2014 2:30 pm Was Immediate Notice Given? If YES, To Whom? Mike Bratcher - OCD, Jeffrey Robertson - BLM By Whom? Amanda Trujillo Date and Hour 8/4/2014 6:15 pm Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.\* Describe Cause of Problem and Remedial Action Taken.\* A split in the polyline caused the release of produced water. The polyline was fused back together and a vacuum truck dispatched to pick up any standing fluids and dispose of at an NMOCD approved facility. Describe Area Affected and Cleanup Action Taken.\* The impacted area was approximately 27' x 300' along the road. Concho had the spill site sampled to delineate any possible contamination from the release and presented a remediation work plan to the NMOCD and the BLM for approval prior to any significant remediation work. All work has been completed in accordance to the approved I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Printed Name: Lupe Carrasco Title: Environmental Coordinator Approval Date: **Expiration Date:**

Conditions of Approval:

gcarrasco@concho.com

Phone:

575-746-2010

E-mail Address:

Date March 13, 2015

<sup>\*</sup> Attach Additional Sheets If Necessary