

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 3/19/2015  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: GJ West Coop #92 Battery	Facility Type: Battery
Surface Owner: State	Mineral Owner:
	API No.

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	17S	29E					Eddy

Latitude 32.80259 Longitude 104.07849

**NATURE OF RELEASE**

Type of Release: Oil and Water	Volume of Release: 9 bbls Oil; 14 bbls PW	Volume Recovered: 8 bbls Oil; 10 bbls PW
Source of Release: Gasket Failure	Date and Hour of Occurrence: 11/20/2014 8:00am	Date and Hour of Discovery: 11/20/2014 8:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Amanda Trujillo	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a gasket failure on a heater treater. The process equipment was repaired and vacuum trucks were dispatched to pick up any standing fluid. All fluid was disposed of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.\*

Most of the released fluid was contained within the lined facility. However there was some impact outside of the lined area to the east of the facility of the pad. Concho had the spill site sampled to delineate any possible contamination from the release and presented a remediation work plan to the NMOCD for approval prior to any significant remediation work. All work has been completed in accordance to the approved work plan and stipulations requested.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Lupe Carrasco	Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: 3/20/2015	Expiration Date: N/A
E-mail Address: gcarrasco@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: March 19, 2015	Phone: 575-748-6940	FINAL

\* Attach Additional Sheets If Necessary

2RP-2641