

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Enterprise Field Services LLC	Contact Dina Babinski
PO Box 4324, Houston, TX 77252	Telephone No. 210-528-3824
Facility Name Pipeline ROW, 30137 Gathering Lateral	Facility Type: Gas Gathering Pipeline
Surface Owner State of New Mexico	Mineral Owner NA - Pipeline
Lease No. NA	

LOCATION OF RELEASE

Unit Letter O	Section 13	Township 19S	Range 28E	Feet from the 60	North/South Line South	Feet from the 144	East/West Line West	County Eddy
-------------------------	----------------------	------------------------	---------------------	----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude: **N 32.653889** Longitude: **W -104.129961**

NATURE OF RELEASE

Type of Release Natural Gas, Pipeline Liquids	Volume of Release: 1647 MCF, 5 BBL Liquids	Volume Recovered: N/A
Source of Release Pipeline Leak.	Date and Hour of Occurrence 09/29/2014 @ 08:40 MDT	Date and Hour of Discovery 09/29/2014 @ 08:40 MDT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, District 2	
By Whom? Osman De Leon	Date and Hour 09/29/2014 @ 10:46 MDT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Pipeline leak was detected by pumper driving by. Pipeline segment was clamped and blown down, and leaking portion was repaired.

Describe Area Affected and Cleanup Action Taken.*

Liquid spill occurred within pipeline ROW. Contaminated soil was excavated and disposed off in an approved landfill. Subsequent soil sampling results demonstrate that cleanup meets NMOCD remediation criteria.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jon E. Fields	Approved by District Supervisor:	
Title: Director, Field Environmental	Approval Date: 5/28/15	Expiration Date: N/A
E-mail Address: jefields@eprod.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 3-16-2015 Phone: 713-381-6684		

* Attach Additional Sheets If Necessary

2RP-2623