

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-CVX-JV-BS #028H; 2RP# 2612	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42393
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	23	24S	30E	590	North	1060	East	Eddy

Latitude: N 32.208892° Longitude: W 103.845917°

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 8 bbls crude oil, 38 bbls produced water with soap	Volume Recovered: 2 bbls crude oil, 23 bbls produced water
Source of Release: Production wellhead	Date and Hour of Occurrence: 11/14/14 @ approx. 11:30 pm	Date and Hour of Discovery: 11/14/14 @ approx. 11:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Emergency services @ approx. 11:30 pm 11/14/14 Jim Amos, BLM and Mike Bratcher, NMOCD	
By Whom? Rig Supervisor and Tony Savoie	Date and Hour: 11/15/14 BLM @ 7:30 am NMOCD @ 7:35 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.*

While performing normal maintenance on the well a sudden and unexpected pressure release released fluid to well pad area.

Describe Area Affected and Cleanup Action Taken.*

The release impacted approximately 13,500 sq. ft. of caliche well pad, the fluid puddled up in an area measuring approximately 4,500 sq. ft. the remainder of the area was misted with fluid that saturated from 1/2 inch to less than 1/8 inch. The free standing fluid was recovered with a vacuum truck. Samples were collected, and based on laboratory analytical data and NMOCD approval: the contaminated soil has been excavated and hauled to a state approved disposal facility, a liner installed over areas of deeper contamination, and the excavation backfilled with clean soil. The spill area has been cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: 	
Printed Name: Bradley Blevins	Approval Date: 6/24/2015	Expiration Date: N/A
Title: Assistant Remediation Foreman	Conditions of Approval: FINAL	
E-mail Address: bblevins@basspet.com	Attached <input type="checkbox"/>	
Date: 6-15-2015 Phone: 432-214-3704		

* Attach Additional Sheets If Necessary

2RP-2612