**Photos of Site Activities** Bass 03 SWD (Palmillo) Final Reclamation Unit Letter F, Section 12, T19S, R28E



Excavation at 2' bgs, facing north/northeast July 10, 2014



Excavation at 2' bgs, facing north/northeast July 10, 2014



Drilling SB2, facing north July 30, 2014



Drilling SB3 (background), facing south July 30, 2014