

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Devon Energy Production Co LP (6137)	Contact: Brian Kuh, Devon Completions Foreman
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575- 616-1540
Facility Name: Near Cotton Draw Unit 214H	Facility Type : Well location – OFF PAD
Surface Owner: State	Mineral Owner: Federal
API No. 30-015-41537	

LOCATION OF RELEASE

Unit Letter C	Section 36	Township 24S	Range 31E	Feet from the 200	North/South Line North	Feet from the 1710	East/West Line West	County Eddy
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude: **32 deg 10' 49.931" N** Longitude: **103 deg 44' 4.25" W**

NATURE OF RELEASE

Type of Release: Produced Water from Trunk Line	Volume of Release: 6 bbls	Volume Recovered: 1 bbl
Source of Release: Water transfer trunk line	Date and Hour of Occurrence 3/18/2015, 2:45 PM	Date and Hour of Discovery 3/18/2015, 2:45 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Artesia – Mike Bratcher BLM Carlsbad – Jim Amos	
By Whom? Brian Kuh, Completions Foreman	Date and Hour: 3/19/15, 8:30 AM – OCD phones out of order 3/20/15, 7:30 AM – voicemail to Mike Bratcher 3/19/15, 8:30 AM – voicemail to Jim Amos	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*


N/A

Describe Cause of Problem and Remedial Action Taken.*

Bosque Supervisor turned on pump to send water to Cotton Draw Unit 214 Poseidon tank. When the water started flowing, the hose separated from the hammer union off of the trunk line causing the spill.

Describe Area Affected and Cleanup Action Taken.* The spill traveled approximately 8 feet to the North, 8 feet to the East, 7 feet to the West, and 22 feet to the South of the point of release. A vacuum truck was used to clean up as much water as possible, approximately 1 barrel. Safety & Environmental Solutions met with Alfredo's Trucking on site to assess the impacted area. The affected area was excavated and backfilled with fresh topsoil and the area returned to grade. It was determined 45 cubic yards of soil was impacted. Impacted soil was removed to Lea Land. Soil samples were sent to Cardinal Laboratories in Hobbs, NM. Results of analysis are included in the closure report (attached).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Denise Menoud	Approved by Environmental Specialist:		
Title: Field Admin Support	Approval Date: 8/4/2015	Expiration Date: N/A	
E-mail Address: Denise.Menoud@dmv.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 8/3/2015 Phone: 575-746-5544	FINAL		

* Attach Additional Sheets If Necessary

2RP-2904