

District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 811 S. First St., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources

Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
 accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU #423H Lact Unit; 2RP# 3049	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-40710	

**LOCATION OF RELEASE**

Unit Letter I	Section 19	Township 25S	Range 30E	Feet from the 1750	North/South Line South	Feet from the 880	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: N 32.113042° Longitude: W 103.914955°

**NATURE OF RELEASE**

Type of Release: crude oil	Volume of Release: 6 bbls	Volume Recovered: 1 bbl
Source of Release: Lact Unit	Date and Hour of Occurrence: 6/3/15 @ unknown	Date and Hour of Discovery: 6/3/15 @ 4 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* Air eliminator on battery LACT unit failed and oil was released. Standing fluids were recovered. Air eliminator was repaired.		
Describe Area Affected and Cleanup Action Taken.* Leak affected approximately 480 square feet of well pad. Samples were collected and sent to Cardinal Labs to be tested. Based on analytical data and NMOCD approval the contaminated soil has been excavated and hauled to a state approved disposal facility, and the excavation backfilled with clean soil.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

**OIL CONSERVATION DIVISION**

Signature: <i>Bradley Blevins</i>	Approved by Environmental Specialist:	
Printed Name: Bradley Blevins	Approval Date: 11/3/2015	Expiration Date: N/A
Title: Assistant Remediation Foreman	Conditions of Approval:	
E-mail Address: bblevins@basspet.com	FINAL	Attached <input type="checkbox"/>
Date: <i>11-2-15</i> Phone: 432-214-3704		

\* Attach Additional Sheets If Necessary

2RP-3049