

## Bratcher, Mike, EMNRD

---

**From:** Gregston, Terry G <tgregsto@blm.gov>  
**Sent:** Tuesday, February 28, 2012 4:21 PM  
**To:** Fred Holmes; Bratcher, Mike, EMNRD  
**Cc:** 'Ron Ragland'; 'Joe Hernandez'; 'Stephen McGhee'  
**Subject:** RE:Skelly B South Unit #274 Tank Battery Backfill Request

Gentlemen,

This notification is in regards to the following location:

Event Name: Skelly B South Unit #274 Tank Battery (as per the C-141 submitted by the operator)  
Event Date: 09/25/11  
Event ID: 11NU127TG  
T17S, R31E, Sec. 28, Unit letter G

We have received your backfill request and sample analysis. The BLM approves backfill of this excavation. Road surfaces should be finished with at least 6 inches of compacted caliche. Please let me know when you are ready for a final site inspection.

**BLM approval of this proposal does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health, or the environment, or if the location fails to reclaim properly. In such an event that location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws/regulations.**

**Terry Gregston**  
Environmental Protection Specialist  
Bureau of Land Management  
620 E. Greene St.  
Carlsbad, NM 88220  
Office (575) 234-5958  
Cell (575) 361-2635  
Fax (575) 234-5927

**Confidentiality Warning:** This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

---

**From:** Fred Holmes [mailto:fred@etechnv.com]  
**Sent:** Tuesday, February 28, 2012 3:30 PM  
**To:** 'Bratcher, Mike, EMNRD'; Gregston, Terry G  
**Cc:** 'Ron Ragland'; 'Joe Hernandez'; 'Stephen McGhee'  
**Subject:** LINN Energy - Skelly B South Tank Battery Backfill Request

Dear Mike & Terry:

1. Attached is the analytical summary map and analytical data for the clearance sampling of the Skelly B South #274 Tank Battery.
2. Grab samples were collected from each corresponding sampling site and depth then placed in certified clean jars, labeled, and custody seals applied. Nitrile gloves were used and changed during each sample collection.
3. Samples were preserved according to the requirements ASATM/EPA requirements. Normal Chain of Custody procedures were observed.
4. LINN is requesting permission to backfill and close the site in accordance with the stipulations for the site.

Thank you for your assistance.

*Fred Holmes*

**Etech Environmental & Safety Solutions, Inc.**

P.O. Box 8469

Midland, Texas 79708-8469

Phone: 432-563-2200

Fax: 432-563-2213

E-mail: [fred@etechenv.com](mailto:fred@etechenv.com)

**CONFIDENTIAL**

*This e-mail message, including any attachments, is intended solely for the individual(s) named above. It contains confidential and/or proprietary information. If you are not the intended recipient, please do not read, copy or distribute it or any information it contains. Please immediately notify the sender by return mail and delete it.*