

**From:** Patterson, Heather, EMNRD  
**To:** ["taylor16@aol.com"](mailto:taylor16@aol.com)  
**Cc:** [Bratcher, Mike, EMNRD](#); [Cordero, Gilbert, EMNRD](#)  
**Subject:** FW: Smith & Marrs  
**Date:** Thursday, November 12, 2015 12:31:00 PM  
**Attachments:** Welch 005.jpg  
Welch 006.jpg  
Welch 007.jpg  
Welch 008.jpg  
Welch 009.jpg  
Welch 010.jpg  
Welch004.jpg

---

Ms. Taylor,

Please review the attached pictures. Our field inspector discovered a spill at the Welch State #7 that appears to have been covered up. The OCD will require a C-141 be turned in for this release as soon as possible. This is to be followed by a remediation plan submitted for OCD approval. We appreciate your attention to this issue.

Thank you,

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Cordero, Gilbert, EMNRD  
**Sent:** Monday, November 09, 2015 3:12 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD  
**Subject:** Smith & Marrs

These pics are of the Welch State # 7. Appears to be a spill that was covered over with caliche and is now soaking through.

Gilbert Cordero  
Compliance Officer  
NMOCD District II  
Office 575.748.1283 ext.114  
Cell 575.626.0830