

## **Bratcher, Mike, EMNRD**

---

**From:** Lara Weinheimer <lweinheimer@rice-ecs.com>  
**Sent:** Thursday, March 14, 2013 11:02 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** 'Hack Conder'; 'Bruce Baker'  
**Subject:** Apache E.L. #5 Battery AD  
**Attachments:** Apache E.L. #5 Battery AD - 5 pt. bottom comp and Lab Data.jpg; 3 5 Pt. Bottom Composite @ 1 ft Lab.pdf; Photo Page 2.docx

Mike, attached in the plat of the 5 point composite taken on 3/6/13. Given the low level of chlorides (1,390 mg/kg) in relation to the initial elevated chloride levels, it is evident that the majority of the high chlorides have been removed from the site. Therefore, we are requesting permission to backfill the site with clean soil. Bruce will contact you shortly to discuss the site to determine a path forward.

Thank you,

Lara

Lara Weinheimer  
Project Scientist  
Rice Environmental Consulting & Safety  
122 W. Taylor  
Hobbs, NM 88240  
(575) 441-0431