

Summary Report

Bill Dougherty
Nadel & Gussman Permian LLC
601 N. Marienfeld
Suite 508
Midland, TX 79701

Report Date: December 1, 2015

Work Order: 15112036



Project Name: Aide State No. 10
Project Number: HT Discharge

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
408815	N Side Area 2.5'	soil	2015-11-19	10:50	2015-11-20
408816	W Side Bowl Area 1'	soil	2015-11-19	10:55	2015-11-20
408817	E Side Bowl Area 2.5'	soil	2015-11-19	11:00	2015-11-20
408818	S Side Comp 2.5'	soil	2015-11-19	12:15	2015-11-20
408819	Background	soil	2015-11-19	12:00	2015-11-20

Sample - Field Code	BTEX				TPH DRO	TPH GRO
	Benzene (mg/Kg)	Toluene (mg/Kg)	Ethylbenzene (mg/Kg)	Xylene (mg/Kg)	DRO (mg/Kg)	GRO (mg/Kg)
408815 - N Side Area 2.5'	<0.0200	<0.0200	<0.0200	<0.0200 Qr	<50.0 B	<4.00
408816 - W Side Bowl Area 1'	<0.0200	<0.0200	<0.0200	<0.0200 Qr	<50.0 B	<4.00
408817 - E Side Bowl Area 2.5'	<0.0200	<0.0200	<0.0200	<0.0200 Qr	<50.0 B	<4.00
408818 - S Side Comp 2.5'	<0.0200	<0.0200	<0.0200	<0.0200 Qr	<50.0 B	<4.00
408819 - Background	<0.0200	<0.0200	<0.0200	<0.0200 Qr	<50.0 B	<4.00

Sample: 408815 - N Side Area 2.5'

Param	Flag	Result	Units	RL
Chloride		290	mg/Kg	50

Sample: 408816 - W Side Bowl Area 1'

Param	Flag	Result	Units	RL
Chloride		<250	mg/Kg	50

Sample: 408817 - E Side Bowl Area 2.5'

Param	Flag	Result	Units	RL
Chloride		<250	mg/Kg	50

Sample: 408818 - S Side Comp 2.5'

Param	Flag	Result	Units	RL
Chloride		<250	mg/Kg	50

Sample: 408819 - Background

Param	Flag	Result	Units	RL
Chloride		290	mg/Kg	50