

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Chase Settle
Address 104 S. 4 th Street		Telephone No. 575-748-1471
Facility Name Lost Tank AIS State #3 Battery		Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-015-26586
------------------------	------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter N	Section 36	Township 21S	Range 31E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.42943 Longitude 103.73303

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 5 B/O & 25 B/PW	Volume Recovered 5 B/O & 25 B/PW
Source of Release Separator	Date and Hour of Occurrence 7/21/2015; AM	Date and Hour of Discovery 7/21/2015; AM
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Ian Dolly, Mathew Hagman, Mark Naranjo & Dana Strang	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 7/22/2015; 12:46 P.M. (Email)	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A dump valve on a separator was stuck open, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 50' X 50' was affected within the unlined/bermed battery. The valves were closed and all of the crude oil and produced water was recovered (100%). A roustabout crew was called to make repairs on the separator. Impacted soils will be excavated /hailed to a NMOCD approved facility. **Depth to Ground Water: > 100' (approximately 110', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on completion of the NMOCD approved work plan, Yates Petroleum requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Chase Settle	Approved by Environmental Specialist:		
Title: NM Environmental Regulatory Settle	Approval Date:	Expiration Date:	
E-mail Address: CSettle@yatespetroleum.com	Conditions of Approval:		Attached ☐
Date: December 10, 2015	Phone: 575-748-4171	2RP-	

* Attach Additional Sheets If Necessary