

## **Bratcher, Mike, EMNRD**

---

**From:** Bratcher, Mike, EMNRD  
**Sent:** Monday, January 11, 2016 4:17 PM  
**To:** 'Lupe Carrasco'; Patterson, Heather, EMNRD; James\_Amos@blm.gov; Shelly Tucker  
**Cc:** Amanda Trujillo Davis  
**Subject:** RE: (Work Plan) West Brushy 8 SWD #1 (30-015-31675)

RE: COG \* West Brushy 8 Fed SWD 1 \* 30-015-31675  
2RP-3353 \* Date of release: 9/13/2015

Lupe,

A Final Report C-141 would be accepted for record only. The release/site would be deferred and remain open in OCD database. It is also noted that this site is approximately 600 yards uphill from, and adjacent to a drainage feature, to the Pecos River.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

**Mike Bratcher**  
NMOCD District 2  
811 S. First Street  
Artesia, NM 88210  
O: 575-748-1283 X108  
C: 575-626-0857  
F: 575-748-9720

---

**From:** Lupe Carrasco [mailto:GCarrasco@concho.com]  
**Sent:** Monday, January 11, 2016 2:04 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; James\_Amos@blm.gov; Shelly Tucker  
**Cc:** Amanda Trujillo Davis  
**Subject:** (Work Plan) West Brushy 8 SWD #1 (30-015-31675)

Mr. Bratcher/Mrs. Patterson,

Attached for your consideration is a work plan for the West Brushy 8 Federal SWD #1. Please feel free to contact me with any questions or concerns.

Thanks!

**Lupe Carrasco**  
Environmental Coordinator  
Concho Resources

Cell: 575-725-0787  
Office: 575-748-6933  
[gcarrasco@concho.com](mailto:gcarrasco@concho.com)

1401 Commerce Drive  
Carlsbad, NM 88220



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

---

**From:** Amanda Trujillo Davis  
**Sent:** Friday, October 23, 2015 1:59 PM  
**To:** Heather Patterson; [Mike.Bratcher@state.nm.us](mailto:Mike.Bratcher@state.nm.us); [James.Amos@blm.gov](mailto:James.Amos@blm.gov); Shelly Tucker  
**Subject:** (C-141 Initial) West Brushy 8 SWD #1 (30-015-31675)

Mr. Bratcher/Mr. Amos,

Attached is a C-141 Initial for your consideration. Please call me if you have any additional questions or concerns.

Thank you,

**Amanda Trujillo Davis**  
Senior Environmental Coordinator  
COG Operating LLC  
Cell: 505.350.1336  
Office: 575.748.6930  
[atrujillo@concho.com](mailto:atrujillo@concho.com)

2407 Pecos Ave.  
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

---

**From:** Amanda Trujillo  
**Sent:** Tuesday, September 15, 2015 6:05 PM  
**To:** Heather Patterson; [Mike.Bratcher@state.nm.us](mailto:Mike.Bratcher@state.nm.us); [James.Amos@blm.gov](mailto:James.Amos@blm.gov); Shelly Tucker  
**Subject:** (Notification) West Brushy 8 SWD #1 (30-015-31675)

Mr. Bratcher,

COG Operating LLC is reporting a release on the West Brushy 8 SWD #1 (30-015-31675)  
Unit A Section 8 Township 26S Range 29E  
The release occurred at 3:00 pm on 9/13/2015.  
Released: 30 bbls Produced Water  
Recovered: 3 bbls PW

The release was caused by a poly flowline. The site is being evaluated for clean-up and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thank you,

**Amanda Trujillo**

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

[atrujillo@concho.com](mailto:atrujillo@concho.com)

2407 Pecos Ave.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.