

Bratcher, Mike, EMNRD

From: Ramirez, Ana O <aramirez01@keyenergy.com>
Sent: Friday, January 15, 2016 9:50 AM
To: Bratcher, Mike, EMNRD
Subject: C-141 final BKE spill 11 21 15 - Key Energy Services
Attachments: Pic Log BKE spill 11 21 15.docx; C-141 final BKE 11 21 15.pdf

Mr. Bratcher,

Please find attach the final C-141 for the spill occurred at the BKE SWD, Eddy County, NM on Nov, 21, 2015. No further remediation action were taken since the release was only 5 bbls on the cement unload slab. The volume was completely recovered at the time of the occurrence and for that reason I am attaching pictures of the site to support corrective actions taken.

Please feel free to contact me if you have any comments or questions.

Thanks,

Ana Ramirez | **Key Energy Services** | Environmental Specialist
6 Desta Dr. Suite 4300 Midland, TX 79705
o: 432.571.7203 | m: 432.234.6959 | aramirez01@keyenergy.com

Doing it the right way. *theKeyWay*. Every time.