

Bratcher, Mike, EMNRD

From: Blevins, Bradley G <Bradley.Blevins@chevron.com>
Sent: Friday, November 22, 2013 9:24 AM
To: Bratcher, Mike, EMNRD; 'Amos, James'
Cc: Blevins, Bradley G
Subject: FW: FW: Spill skelly 952
Attachments: Skelly 952 Initial C-141.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Please find the initial C-141 for the release that occurred on the Skelly 952. 3rd party struck one of our lines while repairing a road. If you have any questions please give me a call.



Bradley Blevins
Chevron Delaware Basin
HE Specialist
Hobbs FMT
Direct 575-391-1462 86424
Cell- 575-441-0341

From: Daniel Dominguez [mailto:ddominguezepi@gmail.com]
Sent: Friday, November 22, 2013 9:08 AM
To: Blevins, Bradley G
Subject: Re: FW: Spill skelly 952

Bradley,

Revised Initial C-141 for Skelly 952 attached.

Sincerely,
ENVIRONMENTAL PLUS, INC.

Daniel Dominguez
Environmental Consultant/Safety Director

Environmental Plus, Inc.
P.O. Box 1558
2100 Avenue 'O'
Eunice, NM 88231
(575) 631-0401 (Cell)

(575) 394-3481 (Office)

(575) 394-2601 (fax)