

TABLE #21
CONCENTRATIONS OF BENZENE, BTEX, TPH & CHLORIDE IN SOIL
SECTION C - SUBSECTION #20

PLAINS MARKETING, LP
FORMER MALJAMAR STATION
EDDY COUNTY, NEW MEXICO
PLAINS SRS: HDO-95-61 FORMER MALJAMAR STATION
NMOCD REFERENCE #: 2RP-2504

SAMPLE LOCATION	SAMPLE DEPTH (BGS)	SAMPLE DATE	SOIL STATUS	METHOD: EPA SW 846-8021B, 5030							METHOD: 8015M			TPH C ₆ -C ₃₅ (mg/Kg)	300.1 CHLORIDE (mg/Kg)
				BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL- BENZENE (mg/Kg)	M.P. - XYLENES (mg/Kg)	O- XYLENE (mg/Kg)	TOTAL XYLENES (mg/Kg)	TOTAL BTEX (mg/Kg)	GRO C ₆ -C ₁₂ (mg/Kg)	DRO C ₁₂ -C ₂₈ (mg/Kg)	ORO C ₂₈ -C ₃₅ (mg/Kg)		
Sec. C - 20 @ 1.5' - N. Wall	1.5'	12/9/2015	In-Situ	<0.0011	<0.0021	<0.0011	<0.0021	<0.0011	<0.0021	<0.0021	<26.3	39.2	<26.3	39.2	-
Sec. C - 20 @ 1.5' - S. Wall	1.5'	12/9/2015	In-Situ	<0.0011	<0.0021	<0.0011	<0.0021	<0.0011	<0.0021	<0.0021	<26.6	<26.6	<26.6	<26.6	-
Sec. C - 20 @ 1.5' - E. Wall	1.5'	12/9/2015	In-Situ	<0.0011	<0.0022	<0.0011	<0.0022	<0.0011	<0.0022	<0.0022	<26.9	78.9	38.5	117	-
Sec. C - 20 @ 1.5' - W. Wall	1.5'	12/9/2015	In-Situ	<0.0011	<0.0022	<0.0011	<0.0022	<0.0011	<0.0022	<0.0022	<26.9	<26.9	<26.9	<26.9	-
Sec. C - 20 @ 2' - Floor	2'	12/9/2015	In-Situ	<0.0011	<0.0021	<0.0011	<0.0021	<0.0011	<0.0021	<0.0021	<26.6	171	44.8	216	7.52
NMOCD Recommended Remediation Action Level				10						50				5,000	1,000

- = Not analyzed.