

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**☐ Initial Report ☒ Final Report

Name of Company: Linn Energy	Contact: EL Gonzales
Address: 2130 W Bender, Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name: JL Keel B #077	Facility Type: Injection

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-28279
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter H	Section 8	Township 17S	Range 31E	Feet from the 1930	North/South Line North	Feet from 714	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	------------------	------------------------	----------------

Latitude: 32.85099 Longitude: -103.88486**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 21 bbls	Volume Recovered: 0 bbls
Source of Release: Pipeline	Date and Hour of Occurrence 07/07/2012 1:00 PM	Date and Hour of Discovery 07/07/2012 1:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher - NMOCD Terry Gregston - BLM	
By Whom? Joe Hernandez	Date and Hour: 07/09/2012 9:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Drove to location, noticed water coming out of ground from 2" fiberglass injection line. Went to Keel B #076 well to close valve to isolate line. 2' x 300 yard area.

Describe Area Affected and Cleanup Action Taken.

Beginning August 5, 2013, DFSI personnel were on site to obtain samples within the leak area. Ten samples were obtained and field sampled for chloride levels, as well as BTEX. The BTEX samples were performed using a Mini Rae Photoionization Detector (PID). All clean field samples under NMOCD and BLM regulatory guidelines were submitted for laboratory analysis at Cardinal Laboratories of Hobbs, NM to obtain confirmation. A work plan was submitted to BLM and NMOCD on November 25, 2015, and approved by NMOCD on December 2, 2015 and by BLM on February 3, 2016. Beginning May 5, 2016, DFSI personnel were on site to excavate the release area to 1' bgs around SP1 and SP2 and to 3.5' bgs at SP4. The excavated area on the pad was backfilled to ground surface with clean imported caliche and contoured to the surrounding area. Within the pasture area, erosion controls were installed to naturally backfill the arroyo during rain events. Contaminated soil was properly disposed of at an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: EL Gonzales	Approved by Environmental Specialist:		
Title: Production Supervisor	Approval Date: 7/15/2016	Expiration Date: N/A	
E-mail Address: elgonzales@linenergy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7/7/2016 Phone: 575-504-8002	FINAL		

* Attach Additional Sheets If Necessary

2RP-1233