

From: [Zack Thomas](#)
To: [Patterson, Heather, EMNRD](#)
Cc: [Bratcher, Mike, EMNRD](#)
Subject: RE: bebop 36 W1MD state #2H
Date: Monday, August 15, 2016 6:27:38 AM
Attachments: image001.png
image002.png
Bebop Leak Map.png
C141- Bebop 36 W1MD State #2H (6-18-16) MOC signed Final.pdf
Bebop Sample Results.pdf

Heather,

Attached are the requested documents. Let me know if you have any questions or concerns. Thank you



Zack Thomas
Environmental Rep.
Mewbourne Oil Company
[PO Box 5270](#)
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252
(575) 602-2188
Email: zthomas@Mewbourne.com



From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]
Sent: Tuesday, July 26, 2016 9:30 AM
To: Zack Thomas
Cc: Bratcher, Mike, EMNRD
Subject: RE: bebop 36 W1MD state #2H

If you're pretty sure you got it clean, just go ahead and grab a couple of samples of the release area. If the samples come back clean, send them in with a Final C-141 and a site map and we should be good.

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Zack Thomas [<mailto:zthomas@mewbourne.com>]
Sent: Tuesday, July 26, 2016 8:08 AM
To: Patterson, Heather, EMNRD
Subject: bebop 36 W1MD state #2H

Heather,

I just looked up this c141 on the OCD imaging website to check on it, and saw that you wanted a remediation proposal by 7-27-16. There really isn't anything to propose. We've already done two different applications of Micro Blaze along with scraping up surface contamination off the pad. Let me know what I need to do. Thanks.



Zack Thomas
Environmental Rep.
Mewbourne Oil Company
[PO Box 5270](#)
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252
(575) 602-2188
Email: zthomas@mewbourne.com

