

**From:** [Zack Thomas](#)  
**To:** [Patterson, Heather, EMNRD](#)  
**Cc:** [Bratcher, Mike, EMNRD](#)  
**Subject:** RE: Mewbourne Audit- Quick Draw 10 G #1 2RP-1868  
**Date:** Thursday, September 08, 2016 8:52:13 AM  
**Attachments:** image001.png  
image002.png  
Cardinal Lab Report Quick Draw 10 G #1 2RP-1868.pdf  
C141- Quickdraw 10 G #1 (8-19-13) MOC Signed Final.pdf

---

Guys,

You were correct about the work done inside the battery in connection with 2RP-2312 having cleaned this spill. I've attached the sample results that I submitted alongside 2RP-2312's sample results. Unfortunately the sample map from 2RP-2312 did not include the sample locations from 2RP-1868 but I assure you it was almost in the exact same area. I understand this may be a little confusing so if you have any questions please call. Thank you.



**Zack Thomas**  
Environmental Rep.  
Mewbourne Oil Company  
[PO Box 5270](#)  
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252  
(575) 602-2188  
Email: [zthomas@Mewbourne.com](mailto:zthomas@Mewbourne.com)



---

**From:** Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]  
**Sent:** Friday, September 02, 2016 2:20 PM  
**To:** Zack Thomas  
**Cc:** Bratcher, Mike, EMNRD; Billings, Bradford, EMNRD  
**Subject:** Mewbourne Audit

Zack,

I have been conducting audits of all the environmental issues in District 2 to help clear our backlog. Mewbourne currently has 9 open RP's, most of which are pretty old. Please go over the attached list and let me know if you have any closure reports or additional information on cleanup efforts.

If you have any questions or concerns, please don't hesitate to call.  
Thank you,

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228