

Burnett Oil Company

6666

Loco Hills, NM

Sample Locations

Gissler A-9

Pre-Treated TPH	Post-Treated TPH 5/9/16	Post-Treated TPH 7/14/16	Pre-Treated Chlorides	Post-Treated Chlorides 5/9/16	Post-Treated Chlorides 7/14/16
--------------------	-------------------------------	--------------------------------	--------------------------	-------------------------------------	--------------------------------------

SP1-0'-1'	15510	12200	1460	3200	-	111
SP1-1'-1.5'	65.5	436	4330	3600	-	663
SP1-2'-2.5'	-	-	85.7	2800	-	431
SP1-3'-3.5'	-	-	391	752	-	478
SP1-4'-4.5'	-	-	2070	-	-	423
SP2-0'-1'	3739	41600	116	128	-	137
SP2-1'-1.5'	-	19300	138	160	-	124
SP2-2'-2.5'	-	183	34.4	-	-	115
SP2-3'-3.5'	-	-	46.9	-	-	103
SP2-4'-4.5'	-	-	68.2	-	-	93.3
SP3-0'-1'	19490	11300	ND	592	-	701
SP3-1'-1.5'	9260	88.5	141	80	-	729
SP3-2'-2.5'	13.5	-	1500	ND	-	635
SP3-3'-3.5'	-	-	76.9	ND	-	551
SP3-4'-4.5'	-	-	86.3	-	-	635
SP4-0'-1'	5519	15600	34.1	1040	-	572
SP4-1'-1.5'	-	15700	184	32	-	678
SP4-2'-2.5'	-	355	923	ND	-	658
SP4-3'-3.5'	-	-	1860	ND	-	613
SP4-4'-4.5'	-	-	357	ND	-	662

Legend

Acceptable	
Near Acceptable	
Unacceptable	
Not Tested	-
Not Detected	ND