From: Zack Thomas

To: Patterson, Heather, EMNRD
Cc: Bratcher, Mike, EMNRD

Subject: RE: Mewbourne Audit- Deleware Ranch SWD 2RP-1723

Date: Monday, September 12, 2016 1:53:41 PM

Attachments: image001.png

image002.png

C141 - Delaware Ranch SWD (7-3-13) MOC signed Final.pdf Delaware Ranch SWD Closure Report (10-2-14).pdf

Heather,

The Delaware Ranch SWD incident is exactly like the * Quick Draw 10 G #1 * 30-015-36500 * 2RP-1868, whereas the leak on 7-3-13 was remediated by a leak that happened later on 10-2-14 / 2RP-2534. Souder Miller handled the work/plan. I've attached the final report for 2RP-2534 and a Final C141 for 2RP-1723. If you have any questions or concerns please call. Thank you.

Zack Thomas

Environmental Rep. Mewbourne Oil Company PO Box 5270 Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252

(575) 602-2188

Email: zthomas@Mewbourne.com



From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]

Sent: Thursday, September 08, 2016 9:09 AM

To: Zack Thomas

Cc: Bratcher, Mike, EMNRD

Subject: RE: Mewbourne Audit- Quick Draw 10 G #1 2RP-1868

RE: Mewbourne * Quick Draw 10 G #1 * 30-015-36500 * 2RP-1868

Zack.

This closure request is approved.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does

not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Zack Thomas [mailto:zthomas@mewbourne.com]

Sent: Thursday, September 08, 2016 8:45 AM

To: Patterson, Heather, EMNRD **Cc:** Bratcher, Mike, EMNRD

Subject: RE: Mewbourne Audit- Quick Draw 10 G #1 2RP-1868

Guys,

You were correct about the work done inside the battery in connection with 2RP-2312 having cleaned this spill. I've attached the sample results that I submitted alongside 2RP-2312's sample results. Unfortunately the sample map from 2RP-2312 did not include the sample locations from 2RP-1868 but I assure you it was almost in the exact same area. I understand this may be a little confusing so if you have any questions please call. Thank you.

Zack Thomas

Environmental Rep. Mewbourne Oil Company PO Box 5270

Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252

(575) 602-2188

Email: zthomas@Mewbourne.com



From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]

Sent: Friday, September 02, 2016 2:20 PM

To: Zack Thomas

Cc: Bratcher, Mike, EMNRD; Billings, Bradford, EMNRD

Subject: Mewbourne Audit

Zack,

I have been conducting audits of all the environmental issues in District 2 to help clear our backlog. Mewbourne currently has 9 open RP's, most of which are pretty old. Please go over the attached list and let me know if you have any closure reports or additional information on cleanup efforts.

If you have any questions or concerns, please don't hesitate to call. Thank you,

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228