

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Wednesday, October 05, 2016 5:03 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: 2RP-351 (Gushwa DR Battery)
Attachments: Gushwa DR Battery (10 08 2009).pdf

I've attached the C-141 Approved Initial Report and the cover letter, Final C-141 and sample diagram for the above location. Agave Energy is conducting remediation work within the release area that occurred on 10/7/2009 and was asking Yates on the status of equipment nearby. I wanted to be able to reference an approved Final C-141 to show that Yates' remediation work was completed.

If you have any questions or need further supporting documentation, please contact me.

Thank you.

Robert Asher
Sr. Environmental Supervisor
Health & Environmental Department
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)
Yates Safety Begins With YOUR Safety

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
