

From: Patterson, Heather, EMNRD
To: "[Sheldon Hitchcock](#)"; [Kimberly M. Wilson](#)
Cc: [Bratcher, Mike, EMNRD](#); [Tucker, Shelly](#); "[Chris Morphew](#)"; jamest@daktoares.com
Subject: RE: Dakota Resources Trigg Fed 1
Date: Wednesday, October 12, 2016 6:29:00 AM
Attachments: image004.png

Sheldon,

You are approved to backfill this location.

Thank you,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Sheldon Hitchcock [<mailto:shitchcock@talonlpe.com>]
Sent: Tuesday, October 11, 2016 3:01 PM
To: Patterson, Heather, EMNRD; Kimberly M. Wilson
Cc: Bratcher, Mike, EMNRD; Tucker, Shelly; 'Chris Morphew'; jamest@daktoares.com
Subject: RE: Dakota Resources Trigg Fed 1

Heather, Shelly,

The TPH and BTEX results for the sidewalls around S-4 are attached. As you will see the North sidewall was above RRAL's during our first sample event. We extended that sidewall to the north another few feet and it is now clean. At this time I would like permission to backfill the excavation.

Respectfully,

Sheldon Hitchcock
Project Manager
Office: 575.746.8768
Direct: 575.616.4021
Cell: 575.689.5198
Fax: 575.746.8905
Emergency: 866.742.0742
Web: www.talonlpe.com



From: Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]
Sent: Friday, September 16, 2016 9:30 AM
To: Kimberly M. Wilson <kwilson@talonlpe.com>

Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Sheldon Hitchcock <shhitchcock@talonlpe.com>; David Adkins <dadkins@talonlpe.com>; Tucker, Shelly <stucker@blm.gov>

Subject: RE: Dakota Resources Trigg Fed 1

Kimberly,

Did you get the confirmation samples for S-4?

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Kimberly M. Wilson [<mailto:kwilson@talonlpe.com>]

Sent: Thursday, September 15, 2016 1:55 PM

To: Patterson, Heather, EMNRD

Cc: Bratcher, Mike, EMNRD; Sheldon Hitchcock; David Adkins

Subject: Dakota Resources Trigg Fed 1

RE: Dakota Resources * Trigg Fed 001 * 30-015-25006 * L-7-21s-28e * Eddy County, New Mexico

NMOCD Tracking Number: **2RP-1814** * Date of release: 8/16/2013

Heather,

Good afternoon. Attached is the site map for the above referenced location. Yesterday I pulled soil samples from the sidewalls (N, S, E) around sample location S-5. I performed field titration for chlorides on site. My results are as follows: North sidewall = 212 mg/kg, South sidewall = 567 mg/kg, East sidewall = 212 mg/kg

On behalf of our client, we would respectfully request permission to begin backfilling operations on this project.

If you have any questions or concerns please feel free to contact me. Thank you.

Kimberly M. Wilson

Project Manager

Office: 575.746.8768

Direct: 575.616.4023

Cell: 575.602.3826

Fax: 575.746.8905

Emergency: 866.742.0742

Web: www.talonlpe.com



