

Received 11/8/2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1621833883

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	MYOX 28 STATE #002H	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-015-39060

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	28	25S	28E	330'	South	330'	West	Eddy

Latitude 32.0942116 Longitude 104.0996017

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	45bbls of Produced Water	Volume Recovered:	43bbls of Produced Water
Source of Release:	1" valve	Date and Hour of Occurrence:	07-29-2016 08:00 am	Date and Hour of Discovery:	07-29-2016 08:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD / Amber Groves - SLO		
By Whom?	Robert Grubbs Jr.	Date and Hour:	Fri 7/29/2016 3:54 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
1" valve was left open on a head switch. Close valve.					
Describe Area Affected and Cleanup Action Taken.*					
This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho had the free fluids and any contaminated material inside the lined facility removed. The liner has been cleaned and returned back to normal operations.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of Pa C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:					
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist: <i>MBratcher</i>			
Title:	Senior HSE Coordinator	Approval Date:	11/8/16	Expiration Date:	N/A
E-mail Address:	rgrubbs@concho.com	Conditions of Approval: N/A			Attached <input type="checkbox"/>
Date:	November 8, 2016	Phone:	432-683-7443	FINAL	

* Attach Additional Sheets If Necessary

2RP-3819