

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 11/28/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report ☒ Final Report

Name of Company: Burnett Oil Co., Inc.	Contact: Johnny Titsworth	
Address: Burnett Plaza-Ste 1500, 801 Cherry St-Unit 9, Fort Worth, TX 76102	Telephone No. (432) 425-2891	
Facility Name: Gissler A 30	Facility Type: Well	
Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-35336

LOCATION OF RELEASE

Unit Letter P	Section 11	Township 17S	Range 30E	Feet from the 330	North/South Line FSL	Feet from the 330	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.84263 Longitude: -103.93511

NATURE OF RELEASE

Type of Release: oil /pw	Volume of Release: 2 bbls/6 bbls	Volume Recovered: 0/0
Source of Release: wellhead	Date and Hour of Occurrence	Date and Hour of Discovery: 2/26/16 0900
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM – S. Tucker & NOMCD – H. Patterson (phone & email)	
By Whom? Leslie Garvis	Date and Hour: 2/26/16 1530	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A


Describe Cause of Problem and Remedial Action Taken.*

Packing on wellhead blew out. packing was replaced and well was put back into service. The impacted area was treated using a bio-remediation process.

Describe Area Affected and Cleanup Action Taken.*

150'x2'-5' area on the pad & 50'x1' area in the pasture to the west and south of the location

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Johnny Titsworth	Approved by Environmental Specialist:		
Title: HSE Coordinator	Approval Date: 12/2/2016	Expiration Date: N/A	
E-mail Address: jtitsworth@burnettoil.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: 11/28/16	Phone: (432) 425-2891		

* Attach Additional Sheets If Necessary

2RP-3589